

NASA Conference Publication 10075

NASA Workshop on Impact Damage to Composites

1N-24

33454

P.476

*Compiled by
C. C. Poe, Jr.
NASA Langley Research Center
Hampton, Virginia*

Proceedings of a workshop sponsored by the
NASA Langley Research Center and held at
Langley Research Center
Hampton, Virginia
March 19-20, 1991

JULY 1991

(NASA-CP-10075) NASA WORKSHOP ON IMPACT
DAMAGE TO COMPOSITES (NASA) 476 p CSCL 110

N91-29240

Unclas
G3/24 0033454

NASA

National Aeronautics and
Space Administration

Langley Research Center
Hampton, Virginia 23665-5225

PREFACE

The *NASA Workshop on Impact Damage to Composites* was sponsored by the Mechanics of Materials Branch of NASA Langley Research Center. The workshop was held on March 19 and 20, 1991 at Langley Research Center, Hampton, Virginia. The objective was to review technology for evaluating damage tolerance of composite structures with impact damage and identify deficiencies. The number of registered participants was 40, representing industry, government, and universities; a list is included. The participants were specialists in the field of impact damage and composites. The workshop was divided into the following five sessions:

- I - Impact Mechanics and Scaling
- II - Damage and Strength Predictions
- III - Standard Tests
- IV - Design Criteria and Certification
- V - Identification of Technology Deficiencies

The review, which was conducted in *Sessions I-IV*, consisted of invited talks that covered research and development, design, and criteria. Technology deficiencies were identified and discussed in Session V. Mr. C. C. Poe, Jr. moderated the sessions. This conference publication is a compilation of the slides used by the speakers in *Sessions I-IV* and a *List of Actions to Address Technology Deficiencies* that were recommended by the participants in *Session V*.

CONTENTS

PREFACE	i
List of Actions to Address Technology Deficiencies	v
List of Speakers and Attendees	vi

Session I - Impact Mechanics and Scaling

Composition and Analysis of the Impact Force Curve	1
Wade C. Jackson, U.S. Army Aerostructures Directorate, USAARTA-AVSCOM	
Impacting Large Composite Structures and Scaling Impact Response and Damage	27
C. B. Madsen, M. E. Morgan, and R. J. Nuismer, Hercules Aerospace/Composite Products	
Effect of Low-Speed Impact Damage on Compression Loaded Composite Structures Marshall Rouse, Aircraft Structures Branch, NASA Langley Research Center (Not available for publication.)	

Session II - Damage and Strength Predictions

Delaminations in Composite Plates under Transverse Static or Impact Loads	79
Scott R. Finn and George S. Springer, Stanford University	
Impact Damaged Composites, Part I: Damage Simulation and Strength Predictions	111
Larry B. Ilcewicz and Ernest F. Dost, Boeing Commercial Airplane Group	
Towards a Methodology for the Assessment of Impact of Composite Structures	163
Paul A. Lagace, Massachusetts Institute of Technology	

Session III - Standard Tests

Standard Impact Tests Used at Lockheed	211
C. E. Griffin, and T. Gillette, Lockheed Aeronautical Systems Co.	
Impact Damaged Composites, Part II: Standard Tests for Fuselage Structural Issues	255
Ernest F. Dost and William B. Avery, Boeing Commercial Airplane Group	
Impact Resistance and Material Toughness	319
John Masters, Lockheed Engineering & Sciences Co.	

Standard Impact Tests	333
Victor L. Chen, Douglas Aircraft Co.	

Session IV - Design Criteria and Certification

Relevance of Impactor Shape to Tension Strength of Thick Carbon/Epoxy with Nonvisible Damage	361
C. C. Poe, Jr., NASA Langley Research Center	
Certification of Composites for Aircraft	401
John Lincoln, Aeronautical Systems Division, Wright-Patterson Air Force Base	
Damage Tolerance of Composites Criteria and Evaluation	421
Ray E. Horton, Boeing Commercial Airplane Group	

LIST OF ACTIONS TO ADDRESS TECHNOLOGY DEFICIENCIES

General

- Standardize philosophy of distinguishing between damage resistance and damage tolerance.
- Standardize coupon type impact test.
- Develop methodology to relate results from standard impact tests of coupons to structures.
- Develop analyses to reduce the amount of testing currently used in the building block approach to verify a design.
- Develop progressive damage analyses.
- Address unique requirements of fuselage type structure.

Damage Resistance

- Develop a measure of extent and degree of impact damage, particularly one that relates to a threshold for detection.
- Develop understanding of strain-rate effects.
- Develop failure criteria to predict damage.
- Determine preload effects.
- Develop method to predict delamination growth in fatigue.
- Determine residual stress effects.
- Develop relationship between ply cracking, interlaminar toughness, and damage resistance.
- Develop local contact stiffness relationship that accounts for damage and other nonlinearities.

Damage Tolerance

- Develop failure criteria.
- Determine effects of biaxial loading and shear loading.

Criteria

- Survey airlines to determine frequency of impacts that can damage composite structures.
- Determine effects of applying limit load cycles to fatigue test article.
- Perform probability analysis to relate factor of safety to level of impact energy.
- Determine if criteria should result in strengths that are very sensitive to changes in level of energy or damage.
- Determine effects of oblique impacts.
- Determine how to account for impactor shape.

LIST OF SPEAKERS AND ATTENDEES

Dr. William B. Avery Boeing Defense & Space Group P.O. Box 3999, M/S 82-32 Seattle, WA 98124-2499	(206) 773-5365 (206) 477-2489 fax
Mr. Charles P. Blankenship M.S. 118 NASA Langley Research Center Hampton, VA 23665-5225	(804) 864-6005
Dr. Victor L. Chen Dept. 1XX, M/C 18-98 Douglas Aircraft Co. 3855 Lakewood Blvd. Long Beach, CA 90846	(213) 496-7415 (213) 982-0815 fax
Mr. H. Benson Dexter M.S. 188B NASA Langley Research Center Hampton, VA 23665-5225	(804) 864-3094
Mr. Ernest F. Dost Boeing Commercial Airplane Co. Advanced Programs Composite Group P.O. Box 3707, M.S. 3T-AU Seattle, WA 98124-2499	(206) 393-9632 (206) 477-2489 fax
Mr. Marvin B. Dow M.S. 188B NASA Langley Research Center Hampton, VA 23665-5225	(804) 864-3090
Dr. Wolf Elber M.S. 266 NASA Langley Research Center Hampton, VA 23665-5225	(804) 864-3956
Gerry Flanagan Grumman Aerospace Corp. MS B44-35 Bethpage, NY 11714	(516) 346-6510 (516) 575-7428 fax
Mr. Tim Gillette Lockheed Aeronautical Systems Co. Dept. 76-41 Bldg. 369 P.O. Box 551 Burbank, CA 91520	(818) 847-7913 (818) 847-2482 fax

Dr. Michael Graves
Massachusetts Institute of Technology
Department of Aeronautics and Astronautics
Technical Laboratory for Advanced Composites
77 Massachusetts Avenue, Rm 33-313
Cambridge, MA 02139

(617) 253-3628
-2465

Dr. Longin Greszczuk
McDonnell Douglas Space Systems
A03/365/13-3
5301 Bolsa Ave.
Huntington Beach, CA 92647

(714) 896-3810

Mr. C. F. Griffin
Lockheed Aeronautical Systems Co.
Dept. 76-41 Bldg. 369
P.O. Box 551
Burbank, CA 91520

(818) 847-7913
(818) 847-2482 fax

Dr. Christian K. Gunther
Boeing Defense & Space Group, Helicopters
MS P30-30
P.O. Box 16858
Philadelphia, PA 19142-0858

(215) 499-9526

Mr. Ray E. Horton
Boeing Commercial Airplane Co.
High Speed Commercial Transport
P.O. Box 3707, M.S. 3T-CH
Seattle, WA 98124-2499

(206) 477-2243

Dr. Jerrold M. Housner
M.S. 240
NASA Langley Research Center
Hampton, VA 23665-5225

(804) 864-4323

Dr. Larry B. Ilcewicz
Boeing Commercial Airplane Co.
Advanced Programs Composite Group
P.O. Box 3707, M.S. 3T-AU
Seattle, WA 98124-2499

(206) 393-9630
(206) 477-2489 fax

Dr. Karen E. Jackson
M.S. 495
NASA Langley Research Center
Hampton, VA 23665-5225

(804) 864-4147

Mr. Wade C. Jackson
M.S. 188E
NASA Langley Research Center
Hampton, VA 23665-5225

(804) 864-3468

Dr. W. Steven Johnson
M.S. 188E
NASA Langley Research Center
Hampton, VA 23665-5225

(804) 864-3463

Mr. Han-Pin Kan
Northrop
1 Northrop Ave.
Code 3853/MF
Hawthorne, CA 90504

(213) 332-5285

Dr. Paul Lagace
Massachusetts Institute of Technology
Department of Aeronautics and Astronautics
Technical Laboratory for Advanced Composites
77 Massachusetts Avenue, Rm 33-303
Cambridge, MA 02139

(617) 253-3628
-2465

Dr. K. Y. Lin
University of Washington
Guggenheim Hall, FS-10
Seattle, WA 98195

(206) 543-6334

Dr. Jack Lincoln
ASD/ENFS
Wright Patterson Air Force Base, OH 45433

(513) 255-6879

Mr. Ozzie Lopez
M.S. 240
NASA Langley Research Center
Hampton, VA 23665-5225

(804) 864-3181

Mr. Carl B. Madsen
Hercules Incorporated
Aerospace Products Group
Bacchus Works, MS N2EA16
Magna, UT 84044-0098

(801) 251-6634
(801) 251-6676 fax

Dr. John E. Masters
M.S. 188E
NASA Langley Research Center
Hampton, VA 23665-5225

(804) 864-3460

Dr. Kevin O'Brien
M.S. 188E
NASA Langley Research Center
Hampton, VA 23665-5225

(804) 864-3465

Mr. C. C. Poe, Jr.
M.S. 188E
NASA Langley Research Center
Hampton, VA 23665-5225

(804) 864-3467

Mr. Marc A. Portanova M.S. 188E NASA Langley Research Center Hampton, VA 23665-5225	(804) 864-3476
Mr. Theodore R. Porter Boeing Military Airplane NS 4A-14 P.O. Box 3707 Seattle, WA 98124-2207	(206) 655-6676
Mr. James Reeder N.S. 188E NASA Langley Research Center Hampton, VA 23665-5225	(804) 864-3456
Mr. Marshall Rouse M.S. 190 NASA Langley Research Center Hampton, VA 23665-5225	(804) 864-3182
Mr. Charles R. Saff McDonnell Aircraft Co. Mail Code 102 1322 P.O. Box 516 St. Louis, MO 63166	(314) 233-8623
Mr. Bharat M. Shah Lockheed Aeronautical Systems Co. D176-41/369/B-6 2777 Ontario Ave. Burbank, CA 91520	(818) 847-9413
Dr. Peter Sjoblom University of Dayton Research Institute 300 College Park Ave. Dayton, OH 45469-0180	(513) 229-3812 (513) 229-3433 fax
Mr. Joseph Soderquist FAA, AIR-103 800 Independence Ave. SW Washington, DC 20591	(202) 267-9585
Dr. George S. Springer Professor and Chairman Department of Aeronautics and Astronautics Stanford University Stanford, CA 94305	(415) 723-4135 (415) 723-0062 fax
Dr. Krishna Srinivasan N.S. 226 NASA Langley Research Center Hampton, VA 23665-5225	(804) 864-4266

Mr. Jim Suarez
Grumman Aerospace Corp.
MS B44-35
Bethpage, NY 11714

(516) 575-6552
(516) 575-7428 fax

Dr. John T. Wang
M.S. 240
NASA Langley Research Center
Hampton, VA 23665-5225

(804) 864-8185


Composition and Analysis of the Impact Force Curve

presented by

Wade C. Jackson

**Mechanics of Materials Branch
NASA Langley Research Center**

Impact Analysis Model



Analysis Methods

Computer Programs

B.V. Sankar (University of Florida)

C.T. Sun (Purdue University)

Energy-Balance Method (Greszczuk)

Zener/Olsson Solution

Mittal's Solution

Computer Programs

Sankar

**Dynamic Green's Function
Series solution**

**Limited to rectangular plates with
simply-supported boundary conditions**

Sun

Finite element method

**Limited to rectangular plates but can
accommodate any boundary conditions**

Energy-Balance Method

$$K.E. \text{ Impacter} = E_{\text{Plate}} + E_{\text{Indentation}}$$

$$\frac{1}{2}mv^2 = \int_0^{\delta_{\max}} F d\delta + \int_0^{\alpha_{\max}} F d\alpha$$

**force-displacement
relationship for plate**

Hertz's Law

$$F = k\delta$$

$$F = n\alpha^{3/2}$$

Final Equation

$$\frac{1}{2}mv^2 = \frac{1}{2} \frac{F_{\max}^2}{k} + \frac{2}{5} \frac{F_{\max}^{5/3}}{n^{2/3}}$$

Zener/Olsson Model

One-parameter dimensionless analytical model.

Contact duration was less than the time required for bending waves to reflect from the boundaries.

Olsson extended Zener's solution to include anisotropic materials.

$$\frac{d^2 \bar{\alpha}}{dt^2} + \frac{3}{2} \bar{\lambda} \bar{\alpha}^{1/2} \frac{d\bar{\alpha}}{dt} + \bar{\alpha}^{3/2} = 0$$

$$\bar{\alpha}(0) = 0 \qquad \frac{d\bar{\alpha}(0)}{dt} = 1$$

$\bar{\alpha}$ = indentation

$\bar{\lambda}$ = dimensionless impact parameter

Mittal's Equation

Solved same problem as Zener but included the effects of shear deformation.

Final non-linear integral equation

$$\bar{F}^{2/3}(\bar{t}) - \bar{t} + \int_0^{\bar{t}} \bar{F}(\bar{t}') \left[(\bar{t} - \bar{t}') + \frac{4\lambda}{\pi} \left\{ \frac{1}{2} \tan^{-1} \left(\frac{\bar{t} - \bar{t}'}{\beta'} \right) + \frac{\beta'}{\bar{t} - \bar{t}'} \right\} \right] d\bar{t}' = 0$$

$\bar{F}$ = dimensionless force

λ = dimensionless impact parameter

β' = dimensionless shear parameter

Singularity

Evaluated using a recursive relationship with a time step of 0.01

Results

Sample Force Histories

Composition of Impact Force Curve

Impact Animations


Correlation between Analyses

Displacements

Effect of Kinetic Energy, Plate Thickness, Shear Deformation, Plate Size, and Boundary Conditions


Sample Force Histories

48 ply, 12.7 x 12.7 cm ss-ss, K.E. = 13.6 J













Composition of Impact Force Curve

48 ply, 12.7 x 12.7 cm ss-ss, K.E. = 13.6 J















Impact Animations



12.7 x 12.7 cm Cl-CI, 13.56 J, $v=1.647$ m/s, 48-ply Quasi





12.7 x 12.7 cm SS-SS, 13.56 J, $v=9.51$ m/s, 48-ply Quasi







12.7 x 12.7 cm SS-SS, 13.56 J, $v=26.715$ m/s, 48-ply Quasi



12.7 x12.7 cm Cl-Cl, 13.56 J, $v = 26.715$, 48-ply Quasi




12.7 x 12.7 cm SS-SS, 13.56 J, v=95.1 m/s, 48-ply Quasi




Correlation between Analyses

48 ply, 12.7 x 12.7 cm ss-ss, K.E. = 13.6 J




Normalized Dynamic Deflections

48 ply, 12.7 x 12.7 cm ss-ss, K.E. = 13.6 J




Effect of Kinetic Energy on Impact Force

48 ply, 12.7 x 12.7 cm ss-ss




Effect of Shear on Impact Force

12.7 x 12.7 cm ss-ss, K.E. = 13.6 J




Effect of Plate Size on Impact Force

48 ply, ss-ss boundaries, K.E. = 13.6 J



Effect of Boundaries on Impact Force

48 ply, K.E. = 13.6 J



Concluding Remarks - Low Velocity

ENERGY-BALANCE:

Very simple to use and understand.

Accurately predicts impact force and displacements in the "low velocity" region.

Accuracy improves as contact duration increases and/or the plate vibration frequencies increase.

A static stress analysis should be adequate to model the impact problem.

Concluding Remarks - High Velocity

ZENER / OLSSON EQUATION:

Predicts force history very accurately and quickly in the "high velocity" region.

Limited to very thin laminates where shear deformation is not important.

MITTAL'S EQUATION:

Will accurately predict the force history for "high velocity" impacts for a given time step.

Solution is not convergent.

Limited to isotropic or quasi-isotropic plates.

Concluding Remarks - General

Impacts can be divided into three regions: low, medium, and high velocity.

Impact force curve can be constructed using an energy-balance and Mittal's equation.

In the "medium velocity" region, a program such as Sun's or Sankar's must be used to describe the impact.

**IMPACTING LARGE COMPOSITE STRUCTURES
AND SCALING IMPACT RESPONSE AND DAMAGE**

**C. B. MADSEN
M. E. MORGAN
R. J. NUISMER**

HERCULES AEROSPACE/COMPOSITE PRODUCTS

NASA WORKSHOP ON IMPACT DAMAGE TO COMPOSITES

19-20 MARCH 1991

IMPACTING LARGE/THICK STRUCTURES

W. T. HUGHES

W. E. WOODMAN

W. E. WOODMAN

THE USE OF FILAMENT WOUND CASES FOR THE SPACE SHUTTLE SOLID ROCKET BOOSTER REQUIRED AN UNDERSTANDING OF THE EFFECTS OF DAMAGE ON CASE PERFORMANCE

- EXTENSIVE HANDLING PRECAUTIONS COULD NOT TOTALLY ELIMINATE ACCIDENTAL IMPACT THREAT
- ACCEPT/REJECT CRITERIA BASED ON QUARTER-SCALES AND JOINT COUPON MATERIAL
- COUPON AND SUBSCALE RESULTS ARE DIFFICULT TO TRANSLATE TO FULL-SCALE SINCE METHODOLOGY IS NOT WELL UNDERSTOOD
- LACK OF REPRESENTATIVE FULL-SCALE IMPACT STRENGTH LOSS DATA WAS IMPETUS BEHIND SECOND PHASE OF DAMAGE CHARACTERIZATION WORK


- THE OBJECTIVE OF THE FWC IMPACT DAMAGE STUDY WAS TO VERIFY THE BURST INTEGRITY OF THE CASE AT VISUAL DAMAGE THRESHOLD (VDT)
- THE SECONDARY OBJECTIVE WAS TO AID IN ESTABLISHING IMPACT DAMAGE DISPOSITIONING TECHNIQUES

 **HERCULES**

SECOND PHASE OF IMPACT CHARACTERIZATION ADDRESSES LACK OF FULL-SCALE DATA AND PREVIOUS CONCERNS ABOUT STRENGTH LOSS BELOW VISUAL THRESHOLD


- ESTABLISH VISUAL DAMAGE THRESHOLD (VDT) ON FULL-SCALE CASES (BOTH PAINTED AND NONPAINTED SURFACES)
- VERIFY WHETHER DAMAGE BELOW THE VDT DEGRADES CASE STRENGTH
- CHARACTERIZE EXTENT AND TYPE OF DAMAGE (FROM A VARIETY OF IMPACT CONDITIONS)
- USING EXISTING ANALYTICAL TECHNIQUES AND DEPLY DATA
 - INTRODUCE KNOWN AMOUNTS OF DAMAGE INTO FULL-SCALE TEST RINGS
 - COMPARE RING PERFORMANCE TO PREDICTIONS
- ASSESS DAMAGE TOLERANCE OF FWC RINGS/CASFS FROM RING TEST DATA

FWC IMPACT DAMAGE INVESTIGATION LOGIC




HERCULES

TEST CONFIGURATION USED FOR FWC PROVIDED REPRODUCIBLE INSTRUMENTED IMPACTS



HERCULES

FWC IMPACT FIXTURE AND INSTRUMENTATION



RINENCIALES

A MAJOR CONCERN IS UNDETECTED (BELOW VDT) DAMAGE THAT COULD REDUCE PERFORMANCE

- WHAT CONSTITUTED "VISIBLE" BECAME A MAJOR DILEMMA
- LOW LEVEL IMPACTS WERE IDENTIFIABLE IF IMPACT EVENT WAS OBSERVED AND LOCATION KNOWN
- ARMALON OVERWRAP TEXTURED IMPRINT PROVED TO BE HIGHLY SENSITIVE TO IMPACTS
- HUMAN FACTORS SUCH AS EYESIGHT, ABILITY, INSPECTION TECHNIQUES, AND LIGHTING COULD INFLUENCE VISUAL THRESHOLD

**MEASURABLE QUANTIFIED DEFINITION OF VISIBLE
DAMAGE THRESHOLD DEVELOPED WITH HELP OF QC
INSPECTION GROUPS**

- FIELD INSPECTORS WOULD NOT KNOW WHERE TO LOOK
- THREE SEPARATE QC TEAMS FOUND 5-MIL DEPRESSIONS 100% OF THE TIME
 - HERCULES
 - MORTON THIOKOL
- DISTURBANCES LESS THAN 5 MILS WOULD BE HARD TO DETECT
- 5-MIL DEPRESSION IS GREATER THAN ARMALON IMPRINT TEXTURE


HERCULES

QUANTITATIVE VISUAL DAMAGE THRESHOLD DEFINED FOR FWC


- VDT IS A VISUALLY DETECTED ANOMALOUS CONDITION ON THE FILAMENT WOUND SURFACE AS COMPARED TO THE ADJACENT COMPOSITE SURFACE. THIS CONDITION INCLUDES IMPRESSIONS, INDENTATIONS, GOUGES, SURFACE FINISH DISTURBANCES, OR FIBER DAMAGE OF DEPTH GREATER THAN 0.005 IN.
- VDT WAS "QUANTIFIED" TO PROVIDE INSPECTORS WITH A MEANS FOR SCREENING WHAT IS FOUND ON A CASE
- VDT LEVELS FOR FWC
 - 1-IN. DIAMETER IMPACTOR - 90 FT-LB
 - 0.5-IN. DIAMETER IMPACTOR - 20 FT-LB
 - THREE-SIDED CORNER IMPACTOR - 10 FT-LB

DAMAGE FROM IMPACT IN QS WAS DIFFERENT THAN IN FS


QS	FS
DELAMINATIONS DETECTED BY NDE AT ALL BUT LOWEST IMPACT LEVELS	NO DELAMINATIONS DETECTED--NDE TECHNIQUES COULD NOT LOCATE/ QUANTIFY DAMAGE (CROSS SECTION MICROSCOPY CONFIRMED NO DELAMINATIONS)
FIBER DAMAGE EXTENDED WELL BEYOND IMPACT SITE ON ALL SIDES	FIBER DAMAGE LOCALIZED UNDER IMPACT SITE
FIBER DAMAGE FOUND IN ALL 11 LAYERS AT SEVERE IMPACT CONDITIONS	FIBER DAMAGE FOUND 6 (OF 31) LAYERS DEEP AT SEVERE IMPACT CONDITIONS



ONLY HIGH LEVEL DAMAGE CAUSED STRENGTH LOSS (10%) ON QS RINGS



THE FWC IS TOLERANT TO HIGH IMPACT LEVELS BASED ON FS RING TESTING



SCALING IMPACT RESPONSE AND DAMAGE

DAMAGE ASSESSMENT FOR COMPOSITE CASES

F04611-86-C-0040



RESULTS OF LITERATURE SEARCH/INDUSTRY SURVEY WERE PRESENTED AT WORKSHOP

- IN CONJUNCTION WITH JANNAF COMPOSITE MOTOR CASE SUBCOMMITTEE MEETING, NASA LANGLEY, 23-27 FEB 1987
- EXPANDED TO 2 DAYS AT AL REQUEST
- ATTENDANCE

INDUSTRY	GOVERNMENT	UNIVERSITY
• HERCULES • THIOKOL • CSD • ASPC • ARC • MDAC • DUPONT • FIBERITE • UNION CARBIDE • GENERAL RESEARCH • MISSION RESEARCH • AVCO	• AFML • AFWL • AFFDL • AFOSR • JPL • NRL • NAVAL ORDINANCE • MICOM • NASA • ARMY MATERIALS LAB	• VPI • DREXEL • DELAWARE • MIT • ALABAMA • DAYTON

- PANEL DISCUSSION



PROBLEM: IMPACT DAMAGE OF COMPOSITE CYLINDERS IS NOT WELL UNDERSTOOD


- Large Number of Parameters Makes Empirical Approach Difficult
- Empirical Approach too Costly for Large Cylinders



OBJECTIVE: GAIN SUFFICIENT UNDERSTANDING TO DESIGN COST EFFECTIVE CYLINDER IMPACT TESTS


- Understanding of Parameter Effects
- Understanding of Scaling Effects

APPROACH: DO SUFFICIENT ANALYSIS UP-FRONT TO DESIGN INTELLIGENT TEST MATRIX

MODEL	FORMULATION	USE
2 DOF SPRING-MASS (R. J. NUISMER)	ASYMPTOTIC EXPANSION OF EXACT SOLUTION 	DEVELOP UNDERSTAND- ING OF QUASI-STATIC/ DYNAMIC TRANSITION
SCALING (J. MORTON)	DIMENSIONAL ANALYSIS	DEVELOP SCALING RULES
STATIC DEFLECTION OF PLATES AND CYLINDERS	CLOSED FORM AND FINITE ELEMENT 	INVESTIGATE DIFFERENCES IN PLATE AND CYLINDER RESPONSE TO IMPACT
PLATE RESPONSE TO IMPACT (D. S. CAIRNS/ S. R. SWANSON)	RAYLEIGH-RITZ TIME-MARCHING SHEAR DEFORMABLE 	QUANTITATIVE PREDICTION OF PLATE TO IMPACT

ANALYSIS RESULTS WERE INSTRUMENTAL IN DESIGN OF TEST MATRIX

- RESULTS FROM 2 DOF SPRING-MASS IMPACT MODEL:
 - "TYPE" OF RESPONSE DEPENDS ON IMPACTOR/TARGET FREQUENCY RATIO
 - "MAGNITUDE" OF RESPONSE ESSENTIALLY PROPORTIONAL TO IMPACTOR VELOCITY
- RESULTS FROM DIMENSIONAL ANALYSIS:
 - SIMULTANEOUS SCALEUP OF BOTH IMPACTOR AND TARGET GEOMETRY WHILE KEEPING MATERIALS AND IMPACTOR VELOCITY CONSTANT, LEADS TO IDENTICAL TARGET STRAINS AND CONTACT PRESSURES
- RESULTS FROM STATIC DEFLECTION MODELS:
 - RESPONSE TO IMPACT OF PLATES AND CYLINDERS CAN BE MADE SIMILAR



EXPERIMENTAL TEST MATRIX BASED ON ANALYSIS RESULTS

- PLATE TESTS (ALL LAYUPS [X/O/O/X])

- IMPACTOR:


- MASS: m AND 64m
- DIAMETER: t, 2t, and 4t
- VELOCITY: v_0 , v_1 , v_2 , AND v_3



2-IN. x 2-IN. x 8 PLYS
($\lambda = 1$)



4-IN. x 4-IN. x 16 PLYS
($\lambda = 2$)



8-IN. x 8-IN. x 32 PLYS
($\lambda = 4$)

- CYLINDER TESTS (ALL LAYUPS [X/O/O/X])



4-IN. DIA ($\lambda = 1$)




13-IN. DIA ($\lambda = 3.3$)




COMPREHENSIVE DATA WAS COLLECTED FROM IMPACT TESTS

- **RESPONSE**
 - **IMPACT FORCE (QUASI-STATIC ONLY)**
 - **DEFLECTION (QUASI-STATIC ONLY)**
 - **STRAINS (SCALED GAGES)**
- **DAMAGE**
 - **VISUAL (FRONTSIDE/BACKSIDE DAMAGE)**
 - **NDE (DIGITAL ULTRASONICS)**
 - **DE (THERMAL DEPLY)**
- **RESIDUAL STRENGTH**
 - **TENSILE COUPONS FOR PLATES (SCALED)**
 - **BURST FOR CYLINDER (4" DIA. ONLY)**



4-IN. TUBE PRESSURIZED SPECIMEN CONFIGURATION FOR RESIDUAL STRENGTH EVALUATION



86C17258


1-1942

ORIGINAL PAGE
BLACK AND WHITE PHOTOGRAPH

SCALED PLATES AND STRAIN GAGES

50

OF FOUR PAGES
ORDERED PAGE 10



09C13123

1-1948

HERCULES

ORIGINAL PAGE IS
OF POOR QUALITY

FLAT PLATE IMPACT HOLDING FIXTURE



HERCULES

8007600

51

ORIGINAL PAGE IS
OF POOR QUALITY

AIRGUN IMPACT TEST FIXTURE




88C7662

HERCULES

1-1987

ORIGINAL PAGE IS
OF POOR QUALITY

**12-IN. CYLINDER IMPACT SITE CONFIGURATION--
TWELVE IMPACTS PER CYLINDER**




89C10483

HERCULES

ORIGINAL PAGE IS
OF POOR QUALITY

PENDULUM IMPACT TEST FIXTURE




89C10482

HERCULES

1-148

ORIGINAL PAGE IS
OF POOR QUALITY

PENDULUM IMPACT EVENT INSTRUMENTATION



89C10483


RESEARCH

1-1988


55

ORIGINAL PAGE IS
OF POOR QUALITY

QUASI-STATIC RESPONSE OF PLATES PREDICTED WELL BY RAYLEIGH-RITZ, SHEAR DEFORMABLE, IMPACT MODEL



DYNAMIC RESPONSE OF PLATES PREDICTED WELL BY RAYLEIGH-RITZ, SHEAR DEFORMABLE, IMPACT MODEL




COMPARISON OF ANALYSIS WITH EXPERIMENT
FOR STRAIN ϵ_x BEHIND IMPACT POINT IN
4-IN. x 4-IN. PLATE, IMPACT VELOCITY
 $v_0 = 4.57$ M/SEC (15 FT/SEC)

PLATE RESULTS OBTAINED SUPPORT CONCLUSIONS FROM 2 DOF MODEL

- "TYPE" OF RESPONSE DEPENDS ON IMPACTOR/TARGET FREQUENCY RATIO (NOT VELOCITY OF IMPACTOR)


2-IN. x 2-IN. FLAT PLATE IMPACT--6-23
HOOP VERSUS TIME (PENDULUM)



QUASI-STATIC RESPONSE (PENDULUM)

$\omega_1 = 1600 \text{ Hz}$
 $\omega_2 = 2260 \text{ Hz}$

IMPACT ON 2-IN. x 2-IN. WITH $v_0 = 3-15$
HOOP NO. 1 VERSUS TIME (AIRGUN)




DYNAMIC RESPONSE (AIRGUN)

$\omega_1 = 12,500 \text{ Hz}$
 $\omega_2 = 2,260 \text{ Hz}$



CYLINDER RESPONSE ALSO FOLLOWS THE FREQUENCY RATIO RULE




RESULTS OBTAINED SUPPORT CONCLUSIONS FROM 2 DOF MODEL

- MAGNITUDE OF RESPONSE ESSENTIALLY PROPORTIONAL TO IMPACTOR VELOCITY (UP TO DAMAGE INITIATION)

- 2 DOF MODEL ACCURATELY PREDICTS CONTACT FORCE IN QUASI-STATIC RANGE


$$F(t) = \sqrt{2k_{eff}} K \sin \sqrt{\frac{k_{eff}}{m_1}} t = v \sqrt{m_1 k_{eff}} \sin \sqrt{\frac{k_{eff}}{m_1}} t$$

4-IN. x 4-IN. FLAT PLATE IMPACT --7-2; FILE: IM72V3
4-IN. x 4-IN. D3--ALL V's



THE TRENDS OBSERVED ON THE FLAT PLATES ARE CONSISTENT WITH THOSE OF THE CYLINDERS


4-IN. TUBE IMPACT TESTS--09D; FILE: 4IN9D
4-IN. D3 ALL V'S




HERCULES

RESPONSE SCALES AS PREDICTED BY DIMENSIONAL ANALYSIS

- KEEPING MATERIALS AND IMPACT VELOCITY CONSTANT WHILE DIMENSIONS OF IMPACTOR AND TARGET SCALEUP BY $\lambda = 1, 2, 4$ RESULTS IN
 - CONSTANT STRAIN
 - CONSTANT CONTACT PRESSURE (FORCE SCALES AS λ^2)
 - IMPACT DURATION INCREASES AS λ




HERCULES




● QUASI-STATIC PLATE
STRAIN RESPONSE
SCALES FOR SCALED
IMPACT

● EVENT DURATION IS
SCALED BY λ AS
PREDICTED BY THE
SCALING RULES








● CONTACT FORCE IS
SCALED BY λ^2 AS
PREDICTED BY THE
SCALING RULES




**CYLINDER STRAIN
RESPONSE SCALES FOR
SCALED IMPACT**


**EVENT DURATION IS
SCALED BY λ AS
PREDICTED BY THE
SCALING RULES**



SIZE EFFECTS APPEAR IN DAMAGE AND STRENGTH SCALING


- IN SPITE OF IDENTICAL STRAINS AND CONTACT PRESSURES, MORE DAMAGE OCCURS AND STRENGTHS GO DOWN AS TARGET GETS LARGER
- DIFFERENT FAILURE MECHANISMS MAY BE AT WORK FOR DIFFERENT TYPES OF DAMAGE
 - DELAMINATION AREA APPEARS TO BE RELATED TO IMPACT ENERGY
 - FIBER BREAKAGE APPEARS TO BE RELATED TO IMPACT STRESS





- DELAMINATION AREAS INDICATE THE FRACTURE MECHANICS SCALING APPROACH IS VALID
- IMPACTOR SIZE HAD NO DISCERNABLE EFFECT
- QUASI-STATIC AND DYNAMIC DOMAINS PRODUCED SIMILAR DELAMINATION DAMAGE






- CYLINDERS FOLLOWED TRENDS SIMILAR TO THOSE OF THE PLATES
- MORE SCATTER WAS FOUND IN THE CYLINDER DELAMINATION DATA THAN IN THE PLATE DATA




FIBER BREAKAGE APPEARS TO BE RELATED TO IMPACT STRESS FOR PLATES




HERCULES

FIBER BREAKAGE DATA FOR CYLINDERS IS LESS CONCLUSIVE BECAUSE OF INCREASED DATA SCATTER



HERCULES

RESIDUAL STRENGTH FOLLOWS DAMAGE SCALING TRENDS FOR PLATES



4-IN. X 4-IN. PLATE VISUAL IMPACT DAMAGE



V1D1



V1D2



V1D3




V2D1



V2D2



V2D3



V3D1



V3D2



V3D3

STANDARD, NON-FLUORESCENT, BLACK AND WHITE
PHOTOGRAPHIC FILM, 35mm, 135, 135, 135, 135

1-4000

HERCULES

4-IN. TUBE VISUAL IMPACT DAMAGE



V1D1




V1D2



V1D3



V2D1



V2D2



V2D3



V3D1



V3D2




V3D3

PHOTOGRAPHED BY
SP-5 J. L. BROWN
SP-5 J. L. BROWN
SP-5 J. L. BROWN


1-100

RESOLUS

TUBE RESIDUAL STRENGTH DATA SUPPORTS DAMAGE TRENDS, WITH IMPACTOR GOEMETRY EFFECTS




**SUPERIMPOSED RESIDUAL STRENGTH DATA FOR 2X2
FLAT PLATES AND 4-IN. TUBES (SAME LAYUP AND THICKNESS)
SUPPORTS FEASIBILITY OF SUBELEMENT APPROACH**



DAMAGE AND STRENGTH SCALING MAY BE ABLE TO BE ACHIEVED THROUGH RESPONSE SCALING WITH REDUCED IMPACT VELOCITIES

- SCALING IMPACTOR AND TARGET GEOMETRIES RESULTS IN SAME "TYPE" OF RESPONSE
- REDUCING IMPACT VELOCITY AS SCALE INCREASES LOWERS APPLIED STRESSES/ STRAINS AND MAY RESULT IN SIMILAR DAMAGE AND STRENGTH LOSS WITH SCALEUP
- PRELIMINARY RESULTS SUGGEST VELOCITY SHOULD SCALE DOWN AS $\lambda^{-1/2}$



HERCULES

CONCLUSIONS



- IMPACTOR/TARGET FREQUENCY RATIO DETERMINES "TYPE" OF IMPACT EVENT (NOT IMPACT VELOCITY OR IMPACTOR/TARGET MASS RATIO)
- SIMPLE PLATE MODEL OF IMPACT ACCURATELY PREDICTS RESPONSE (STRAINS, CONTACT FORCE AND DEFLECTION)
- DIMENSIONAL ANALYSIS ACCURATELY PREDICTS RESPONSE SCALING
- DAMAGE SCALING IS MORE COMPLICATED BUT MAY BE POSSIBLE USING RESPONSE SCALING LAWS WITH REDUCED IMPACT VELOCITIES
- PRELIMINARY RESULTS INDICATE SIMILAR PLATE AND CYLINDER RESPONSE TO IMPACT



**DELAMINATIONS IN COMPOSITE PLATES
UNDER TRANSVERSE
STATIC OR IMPACT LOADS**

Scott R. Finn and George S. Springer

**Department of Aeronautics and Astronautics
Stanford University
Stanford, California 94305**

STATIC**DYNAMIC (IMPACT)**

**non-penetrating
edges clamped, simply supported, or free**

OBJECTIVE

A MODEL TO PREDICT:

- **Damage Initiation Load**
- **Delamination**

Locations

Sizes

Shapes

NEED:

- **Stress Analysis**
- **Damage Model**

understanding of phenomena

data

DAMAGE INITIATION

- **OBSERVATION: Delaminations Accompanied by Matrix Cracking**
- **POSTULATE: Matrix Cracking is a Precursor to Delamination**

Initiation Load when Matrix Cracking Occurs

a) Gosse, et al

$$\frac{1}{2}(\sigma_{yy} + \sigma_{zz}) + \sqrt{\frac{1}{4}(\sigma_{yy} - \sigma_{zz})^2 + \sigma_{yz}^2} \geq Y$$

b) 3-D Tsai-Wu

c) 3-D Hashin

DELAMINATION



POSTULATES




- Matrix Cracking Must Be Present
- Crack Must Open
- Sufficient Strain Energy Available to Cause Delamination




$$\hat{S} \geq \Gamma dA$$





function of stresses
























$$S_t dV_t + S_b dV_b \geq \Gamma dA$$

ANALYSIS - SOLUTION

- **STRESS ANALYSIS**

Modified Wu-Springer Finite Element Method

**Each Edge: Free, Simply Supported, or
Clamped**

Static or Dynamic Load

Load Applied Over Finite Area


**Use Plate Symmetry for Computational
Speed**

- **DELAMINATION**


Step by Step

- **USER FRIENDLY COMPUTER CODES**


delaminated area



IMPACTOR VELOCITY (in/sec)




CONTACT FORCE (lb)




DISPLACEMENTS at TIME = 25 μ sec


UPPER SURFACE



MID-SURFACE









LOWER SURFACE



x_1 COORDINATE (in)

x_2 COORDINATE (in)







STRESSES (ksi)



0 100 200
TIME (μ sec)

0 100 200
TIME (μ sec)

STRAINS (in/in)



0 100 200
TIME (μ sec)

0 100 200
TIME (μ sec)

COMPUTER CODES

- **STRESS ANALYSIS (IMPACT)**
- **DELAMINATION ANALYSIS (DELAM-TRL)**
- **COMBINED STRESS AND DELAMINATION ANALYSIS (IMPACT-ST)**

USER FRIENDLY


TESTS


OBJECTIVE:

- **To Obtain Comprehensive, Systematic Data Set**
 - **To Gain Understanding of the Phenomena**
 - **Verify Present Model**
 - **Verify Future Models**

STATIC


DYNAMIC





test specimen

sensor locations



TESTS

Materials (all ICI/Fiberite) :

T300/976 (Thermoset)

IM7/977-2 (Toughened)

APC-2 (Thermoplastic)

IMPACT

V = 50-225 in/sec

m = 0.355 - 0.963 lbm

R = 0.125, 0.25 in.

L = 4 in.

STATIC

E = 0 - 65 lbf-in

R = 0.25, 0.5, 1.0 in.

L = 3, 4, 5 in.

DAMAGE INSPECTION

C-Scan

X-Ray

Microscope (sections)

MEASUREMENTS

- **Damage Initiation Load**
- **Occurrence of Matrix Cracking**
- **Delamination**

Shapes

Sizes

Locations



Illustration of a typical C-scan result





Illustration of a typical x-ray result

EFFECTS INVESTIGATED

- **Thickness of Bottom Ply Group**
- **Mismatch Angle**
- **Plate Thickness**
- **Nose Radius**
- **Plate Length**


STATIC

Delamination Length, l_D (in)



IMPACT

Delamination Length, l_D (in)




T300 / 976
[0₄/90₄]_s

STATIC

IMPACT

Width Coordinate, x_2 (in)



SUMMARY

- **Tests**

 - Insight**

 - Large Data Set**

- **Damage Initiation Model**

- **Delamination Model**

- **User Friendly Codes**

 - Engineering Design Tool**

- **Verification**

**IMPACT DAMAGED COMPOSITES,
PART I: DAMAGE SIMULATION AND
STRENGTH PREDICTIONS**


Larry B. Ilciewicz

and

Ernest F. Dost

Boeing Commercial Airplane Group

Impact Damaged Composites, Part 1: Damage Simulation and Strength Predictions



Types of Impact Damage States

Damage Simulation & CAI Strength Prediction

E. Dost

Part 1 Summary

Impact Damaged Composites, Part 2: Standard Tests for Fuselage Structural Issues

Fuselage Impact Damage Characterization

E. Dost

Standard Specimen Tests for Fuselage Applications

Part 2 Summary

W. Avery

Impact Damaged Composites, Part 1: Damage Simulation and Strength Predictions

L. Ilcewicz, 3/19/91

Transport Fuselage Structures

Loads and Technical Issues


Problem Definition

A Need to Understand Fundamentals

Damage Resistance versus Damage Tolerance

Silver Bullet Syndrome

Fuselage Section Used for ATCAS Studies




767-X - Sec.46

- Use actual 767-X loads

NASA/BOEING
ATCAS

AL 1823.02 GP-13

Design Drivers for Composite Fuselage




Program addresses critical structural issues.


NASA/BOEING
ATCAS

AL 1023.24 DR 10

Critical Compression Load Condition in Keel and Lower Side Quadrants Aft of Wheel Well (Note Load Redistribution Near Keel Beams and Major Cutouts)




(Note Load Redistribution Near Keel Beams and Major Cutouts)



Problem Definition

- ***Fundamental Understanding of Material Failure Mechanisms***
 - Damage = $f(\text{Impact Variables})$
 - Combined Loads
- ***"Engineering" Analysis Methods Verified By Tests***
 - Damage Simulation
 - Failure Criteria
- ***Identify Critical Impact Threats for Fuselage Structure***
 - Critical Damage = $f(\text{Fuselage Location})$
 - Design Criteria (ULTIMATE, LIMIT, SAFE FLIGHT)
- ***Methods to Relate Coupon Screening Tests to Structural Performance***
 - Material Selection

Material Models and Damage Characterization Tests are Needed to Understand the Critical Impact Threat for New Material Forms



**Issues that Should be Addressed to Make Material Selections
that are Both Economically & Structurally Sound**

**Additional Tests and Analysis Needed to Evaluate the
Relationship Between Coupon and Structural Performance**

Effect of Criteria Must Be Understood, e.g.,

Impact Level

Impact Location

Damage Type and Size

Effect of Scale Must Be Understood, e.g.,

Impact Boundary Condition


Finite Width Effects

Changing Failure Mechanisms


Interactions With Material Dimensional Scales

Relationship Between Material Screening Test Results and Structural Performance

Notched Tensile Strength




Notched Plate Stress Distributions and Tow Material Dimensional Scale




A Need to Understand Fundamentals in Four Areas

Damage Resistance Versus Damage Tolerance




Experimental Data Showing Postimpact Compression Performance as a Function of Laminate Stacking Sequence



Boeing ATCAS Goals in Studying Impact Damaged Composites

- *Identify Critical Impact Threats for Fuselage Structure*
- *Characterization of Important Features of Damage State*
- *Damage Simulation That Works for Coupons and Structures*
- *Predict Residual Strength for Different Load Combinations*


Damage Tolerance: Impact Damage and Through Penetration



NASA/BOEING
ATCAS

Resin Rich Interlaminar Layer Architecture

ORIGINAL PAGE
BLACK AND WHITE PHOTOGRAPH




IM7/8551-7

T800H/3900-2





Compressive Damage Tolerance of Three Materials

Standard Quasi-Isotropic Layup, Ply Thickness = 0.0074 in.


Critical Undamaged Compressive Strain = 0.009 in/in



Interlaminar Toughness is Critical to Impact Damage Resistance



Three Parts to a Damage Tolerance Curve Dominated by Sublaminar Stability



Analysis Curves for IM7/BS51-7

Ply Thickness = 0.0074

Standard Quasi-Isotropic Layup

Corrected to Infinite Width

Beware of Alternate Failure Modes for New Material Forms


Toughened, Resin-Rich Interlaminar Layer for Shear Delamination Resistance Without Compromising Hot/Wet Requirements

- Evidence of Strong Increase in Mode II Toughness With Increasing Load Rate
- Localized Fiber Failure May Have Differing Relationships With Impact Variables

Laminate Stitching to Enhance Sublaminar Stability With Traditional "Brittle" Matrix Systems

- Should Consider Angle Impact and Larger Diameter Impactor for Fiber Failure
- What About Flat Part of Damage Tolerance Curve (Large Through Penetrations)

Shape of Sublaminate Stability Curve for Damage in Standard Coupon



Impact Damaged Composites, Part 1: Damage Simulation and Strength Predictions

Transport Fuselage Structures

L. Ilciewicz

A Need to Understand Fundamentals

Types of Impact Damage States

Damage Simulation & CAI Strength Prediction

E. Post

Part 1 Summary

Impact Damaged Composites, Part 2: Standard Tests for Fuselage Structural Issues

Fuselage Impact Damage Characterization


E. Dost

Standard Specimen Tests for Fuselage Applications

W. Avery


Part 2 Summary

Potential Impact Damage States



NASA/BOEING
AICAS

Cross-Sections of Impacted Specimens Demonstrating Failure Modes



Localized
fiber failure



Delamination and
transverse cracks

A Comparison of Front and Back Surface Pulse-Echo C-Scans for Two Material Types



Front


Back

IM7/8551-7
(45.0,-45.90) 3S


T300/934
(45.90,-45.0) 3S

Aircraft Fuselage Critical Load Conditions

	Critical Load Condition
	Pressure Only
	Pressure With Tension Induced From Flight Loads
	Pressure With Compression Induced From Flight Loads
	Pressure With Shear Induced From Flight Loads
	Shear Induced From Flight Loads




Characteristic Damage State Caused by Impact



ACDP10 Ply 1

0 deg Tool Side



Scale factor 1 in = 0.67 in


Stacking sequence: (-45/0/45/90)




Direction of ply: -45 deg



Ply 2



- Transverse crack descending through previous ply
- - - Transverse crack descending through to next ply
- Delamination on surface of current ply




Direction of ply: 0 deg



Ply 3



- Transverse crack descending through previous ply
- - - Transverse crack descending through to next ply
- Delamination on surface of current ply



Direction of ply: 45 deg



14.000000 0.00

Ply 4




- Transverse crack descending through previous ply
- - - Transverse crack descending through to next ply
- Delamination on surface of current ply



Ply 5




- Transverse crack descending through previous ply
- - - Transverse crack descending through to next ply
- Delamination on surface of current ply



Direction of ply: -45 deg



Ply 6



- Transverse crack descending through previous ply
- - - Transverse crack descending through to next ply
- ▨ Delamination on surface of current ply



Direction of ply: 0 deg




14,1000.25 / 15

Ply 7



- Transverse crack descending through previous ply
- - - Transverse crack descending through to next ply
- Delamination on surface of current ply




Direction of ply: 45 deg



Ply 8



- Transverse crack descending through previous ply
- - - Transverse crack descending through to next ply
- Delamination on surface of current ply



Direction of ply: 90 deg



HL 19003.27 R 1h

Sublaminates for (-45,0,45,90)ns Laminates




NASA Langley
A1AS

C16448.07


Sublamine Buckling Model



(a) Plan view




(b) Section A-A



(c) Free body diagram of the sublamine


STAGSC-1



Verified by

Buckling of a sublamine in a quasi-isotropic composite laminate, K. N. Shivakumar and J. D. Whitcomb, NASA TM 85755, February 1984


Reduced Stiffness Calculation




Assumptions:

1. Load carried by damaged area becomes constant following local buckling
2. Strain compatibility between damaged and undamaged material at failure

Strain Distribution Near Damaged Region



*Predictions and Experimental Results for 12.7-cm Wide Specimens
AS6/3501-6, (45/0/-45/90)_{5S}, and Ply Thickness = 0.0188 cm*



Journal of the American Statistical Association
and Statistical Society of America



Volume 100, Number 1, February 1995
ISSN 0162-1459

Experimental Displacement and Strain Contours IM7/8551-7, (45,90,-45,0)_{2S}, Damage Diameter = 1.28 in.



Actual Displacement Field, Specimen IM7/7-1-1, 23000 lb



0	0.0000-02 to 0.0010-02	0	0.0000-02 to 0.0010-02
1	0.0010-02 to 0.0020-02	1	0.0020-02 to 0.0030-02
2	0.0020-02 to 0.0030-02	2	0.0030-02 to 0.0040-02
3	0.0030-02 to 0.0040-02	3	0.0040-02 to 0.0050-02

Actual Strain Field, Specimen IM7/7-1-1, 23000 lb

Measured Strain Concentration at 80% of failure is between 1.19 and 1.72
Calculated Strain Concentration at failure is 1.92

Experimental Displacement and Strain Contours IM7/3501-6, (45,90,-45,0)_{3S}, Damage Diameter = 2.6 in.



Actual Displacement Field, Specimen IM7/3501-6, 1.2500 in



Actual Strain Field, Specimen IM7/3501-6, 1.2500 in

Actual Strain Field, Specimen IM7/3501-6, 1.2500 in

Measured Strain Concentration at 80% of failure is between 2.9 and 6.6
Calculated Strain Concentration at failure is 4.4

Diameter of Buckled Region vs. Normalized Load IM7/3501-6, (45,90,-45,0)_{3s}







**Fig. 2 Predictions and Experimental Results for 10.2-cm Wide Specimens
T800H/3900-2, (45/0/-45/90)_{3S} and Ply Thickness = 0.0194 cm**




**Predictions and Experimental Results for 10.2-cm Wide Specimens
T800H/3900-2, (45/0/-45/90)_{4S} and Ply Thickness = 0.0151 cm**



Sublaminar Stability/Reduced Stiffness Predictions of CAI for Laminate Layup: $(45_3, 90_3, -45_3, 0_3)_S$




STAGSC-1 Finite Element Grid



HL1008A.11

LVDT Measured Specimen Stability *Laminate Layup: (45₃/90₃/-45₃/0₃)_S*



Summary

- Characteristic damage states (CDS) were classified for impacted laminates
- Local fiber failures and matrix damage were found to compete for dominance of the CDS in a toughened material with small damage
- Test data on compression after impact (CAI) performance versus drop weight impact energy indicated a strong effect of stacking sequence
- Delaminations in the CDS were determined using ultrasonics
- CAI for laminates with symmetric size distributions of matrix damage through the thickness was predicted with a sublaminare stability/stress redistribution analysis method
- Post-impact performance for laminates with unsymmetric size distributions of matrix damage through the thickness was best termed a change in specimen stability, requiring geometrically nonlinear analysis

TOWARDS A METHODOLOGY FOR THE ASSESSMENT OF IMPACT OF COMPOSITE STRUCTURES

PAUL A. LAGACE



TECHNOLOGY LABORATORY FOR ADVANCED COMPOSITES
DEPARTMENT OF AERONAUTICS AND ASTRONAUTICS
MASSACHUSETTS INSTITUTE OF TECHNOLOGY
CAMBRIDGE, MASSACHUSETTS 02139

GOAL

*Develop a consistent methodology (philosophy)
to assess composite structures subjected to impact*


TWO MAJOR ISSUES

Damage Resistance: Measure of the damage incurred by a material/structure due to a particular event.

Damage Tolerance: Measure of the ability of a material/structure to "perform" (given particular requirements) with damage present.

MODULARIZED APPROACH OVERVIEW

166




DAMAGE


RESISTANCE

RESPONSE OF LAMINATE TO IMPACT DIVIDED INTO LOCAL AND GLOBAL RESPONSES

168



IMPACT EVENT GLOBAL MODEL




Assumed Modes Rayleigh - Ritz Analysis

- Reissner - Mindlin Plate Theory (shear deformation)
- Nonlinear Forcing Function (Hertzian Spring)
- Effect of In - Plane Loading (N_x , N_y , N_{xy})
- Bending - Twisting Coupling (D_{16} , D_{26} terms)


Newmark Beta implicit time marching scheme

GLOBAL DYNAMIC RESPONSE IS WELL-PREDICTED




- Y. Qian and S.R. Swanson, "Experimental Measurement of Impact Response in Carbon/Epoxy Plates", Proceedings of the 30th AIAA/ASME/ASCE/AHS Structures, Structural Dynamics and Materials Conference, 1989.

MODULARIZED APPROACH OVERVIEW




LOCAL CONTACT PROBLEM SOLUTION APPROACH



- Constitutive properties smeared through-the-thickness
- Axisymmetry assumed
- D'Alembert inertial terms included in z -direction
- Stress function utilized
- Contact and body forces expanded as Fourier-Bessel series


Resulting strains rotated into ply principal axes

LOCAL STATIC INDENTATION RESPONSE IS WELL-PREDICTED



MODULARIZED APPROACH OVERVIEW

174



DAMAGE PREDICTIONS

- Applied on a ply-by-ply-basis

- Maximum Strain Criterion:

$$\frac{\epsilon_{11}}{\epsilon_{11,ult}} > 1$$

$$\frac{\gamma_{12}}{\gamma_{12,ult}} > 1$$

$$\frac{\epsilon_{22}}{\epsilon_{22,ult}} > 1$$

$$\frac{\gamma_{13}}{\gamma_{13,ult}} > 1$$


$$\frac{\epsilon_{33}}{\epsilon_{33,ult}} > 1$$

$$\frac{\gamma_{23}}{\gamma_{23,ult}} > 1$$

- Mode of failure indicated

SPECIFIC EXAMPLE

176



Layup

- AS4/3501-6 Graphite / Epoxy
- [$\pm 45/0$]_{2S}

Geometry


- Length = 190 mm
- Width = 70 mm
- Clamped (x) - Free (y)

Impact

- 12.7 mm diameter steel sphere
- Impact Energy = 8 Joules
- Impact Speed = 43 m/s

PLY-BY-PLY DAMAGE PREDICTIONS

$[\pm 45/0]_{2S}$




NDE RESULTS

[±45/0] 2S AS4/3501-6 Graphite/Epoxy
190 mm x 70 mm Clamped (x) - Free (y)
12.7 mm diameter steel sphere
at 42.8 m/s impact speed (7.95 Joules)




X-Ray Photograph
(DIB enhanced)



Ultrasonic C-Scan
(pulse-echo)

NDE RESULTS

[±45/0] 2S AS4/3501-6 Graphite/Epoxy
190 mm x 70 mm Clamped (x) - Free (y)
12.7 mm diameter steel sphere
at 42.8 m/s impact speed (7.95 Joules)



X-Ray Photograph
(DIB enhanced)





Ultrasonic C-Scan
(pulse-echo)

INTEGRATED DAMAGE IS WELL-PREDICTED

180

CLAMPED(X) - FREE(Y)



IMPORTANT FACTORS IN DAMAGE RESISTANCE

- It is necessary to treat impact at both the local and global levels (*they can be separated*)
- Parameters have influence in different regimes
 - lower velocity: boundary conditions important
 - higher velocity: constituent mass plays a dominant role*response length versus span is key*
- Impactor energy is not the only controlling factor
mass and velocity must be specified
- Presence of damage can affect local response
ability of surface to conform to indenter is important
- Preload does affect damage resistance

MATERIAL INFLUENCE ON DAMAGE RESISTANCE

- Mass and layup affect structural properties, inertia, and thus the impact event
- Basic material strengths control resulting damage near impactor


Damage resistance is a combined material/structural property

NEEDS

DAMAGE RESISTANCE

- Include more details in local contact stiffness (material nonlinearities and damage)
- Include high strain rate material properties (especially for high strain-to-failure systems)
- incorporate influence of preload
- Acquire better failure criteria
- Determine need to do progressive damage analysis
- Extend general methodology to more complicated structure (once modes of structures are known, structure can be analyzed in this manner)
- Use analysis to do proper scaling

METHODOLOGY CAN BE APPLIED TO SANDWICH CONSTRUCTION




ALL DAMAGE POSSIBILITIES MUST BE CONSIDERED


- **Facesheet damage**
 - front
 - back
- **Core damage**
- **Debond damage**
- **Damage combinations**

DAMAGE TOLERANCE

MODULARIZED APPROACH OVERVIEW



POST-IMPACT RESIDUAL STRENGTH IS A FUNCTION OF DAMAGE PRESENT



FRACTURE OCCURS AT TWO LEVELS

- **Global level** (*structural dominated*)

Failure as a result of structural mechanism (especially under compression)

- **Local level** (*material property*)

Failure initiates from local fracture

SANDWICH CONSTRUCTION INTRODUCES MANY POTENTIAL FAILURE MODES

190


<u>1. Overall Buckling</u> 	<u>4. Facesheet Buckling: Core Compression Failure</u> 	<u>7. Core Flexural Crushing</u> 
<u>2. Core Shear Crimping</u> 	<u>5. Facesheet Ply Buckling: Interlaminar Failure</u> 	<u>8. Core Transverse Shear Failure</u> 
<u>3. Facesheet Buckling: Adhesive Bond Failure</u> 	<u>6. Facesheet Fracture</u> 	<u>9. Core Local Crushing</u> 

DIFFERENT ANALYSES NEEDED FOR VARIOUS LOADING TYPES/POTENTIAL FAILURE MODES

- Many different types of damage occur
 - transverse cracks
 - delaminations
 - fiber fracture
 - others (just beginning to be defined)
- Many different modes of failure/fracture possible
 - depends on geometrical configuration
 - depends on loading
- Each damage type and mode requires consideration
- Requires medium mechanics (ply level) or micromechanics approach


TENSILE RESIDUAL STRENGTH

MODULARIZED APPROACH OVERVIEW



DAMAGED LAMINATE STRAIN ANALYSIS

EQUIVALENT MEMBRANE MODEL (anisotropic inclusion)




Model Based on Lekhnitskii's Complex Potentials

DEGRADATION ASSUMPTIONS

- Delaminations and isolated angle ply splits do not cause significant degradation under tensile loading
- Only fiber breakage creates a significant reduction in constitutive properties
- All elastic constants set to zero in region of fiber breakage

MODULARIZED APPROACH OVERVIEW

196



RESIDUAL STRENGTH PREDICTION FOR IN-PLANE FRACTURE

- Utilize strain from Equivalent Membrane Model
- Average strain concept applied on laminate basis
- Maximum 0° fiber strain assumed to control failure



$$S.R. = \frac{\bar{\epsilon}_x^0}{\frac{1}{a_0} \int_0^{a_0} \bar{\epsilon}_x(x,y) dx}$$

where $\bar{\epsilon}_x^0$ = far field laminate strain

$\bar{\epsilon}_x(x,y)$ = strain distribution

a_0 = material parameter (3.8 mm here)

IN-PLANE FRACTURE IS REASONABLY WELL-PREDICTED




COMPRESSIVE RESIDUAL STRENGTH

PREDICTION METHODOLOGIES FOR COMPRESSIVE RESIDUAL STRENGTH

- A significant amount of work has been published on the compressive residual strength of notches, holes, and imbedded delaminations.
- Very little has been published on multiple imbedded delaminations or combined damage (i.e. impact).
- The effect of impact on compressive residual strength cannot be estimated by an "equivalent-sized" notch, hole, imbedded delamination, or some combination thereof.
- Two-dimensional planform damage information is not sufficient to predict compressive residual strength due to impact.

A MINIMUM COMPRESSIVE RESIDUAL STRENGTH (due to impact) EXISTS




What damage state governs this minimum point?

Is this minimum point a laminate characteristic or is it dependent upon impact method?

GENERAL TEST PROCEDURES


- $[\pm 45/0]_{2S}$ laminate of AS4/3501-6 graphite/epoxy
- 12.7 mm diameter spherical impactor
- Impact coupon and inspect damage
- Bond damaged coupon and an undamaged coupon to aluminum honeycomb base
- Test configuration quasi-statically in compression

COMPRESSION TEST SPECIMEN




TEST DATA SHOWS MINIMUM EXISTS

204



MINIMUM APPEARS TO BE INDEPENDENT OF IMPACTOR MASS

Δ $m = 8.4$ gm $\diamond$ $m = 0.6$ kg $\square$ $m = 1.5$ kg $\blacklozenge$ 12.7 mm hole $\blacksquare$ 25.4 mm hole




NEEDS

DAMAGE TOLERANCE

- Develop progressive damage model for in-plane failure
- Model "actual" damage
- Develop a repertoire of damage tolerance tools for each failure mode (especially structural failure)

EXTEND METHODOLOGY TO STRUCTURAL CONFIGURATIONS



SUMMARY

- A modularized framework and consistent approach for the treatment of composite structures subjected to impact have been developed
- Some refinement of impact analysis is needed
- Integrated through-the-thickness representations (planform) of the damage are generally inappropriate for residual strength predictions
- Modelling the actual (3-D) damage distribution is essential
- A minimum compressive residual strength exists which may be independent of impactor mass

SUMMARY (cont.)

- Development of damage "metrics" is needed
- Need to develop a repertoire of tools for residual strength assessment
- Development of better failure criteria is key in damage resistance and damage tolerance assessments

STANDARD IMPACT TESTS USED AT LOCKHEED

C. F. GRIFFIN
T. GILLETTE

NASA WORKSHOP ON IMPACT DAMAGE TO COMPOSITES
MARCH 19-20, 1991
LOCKHEED AERONAUTICAL SYSTEMS COMPANY

AGENDA

- **LAMINATE IMPACT TESTS**
- **SUBCOMPONENT IMPACT TESTS**
- **COMPONENT IMPACT TESTS**

LAMINATE IMPACT TESTS


PURPOSE:

- **QUANTITATIVE EVALUATION OF THE DAMAGE TOLERANCE OF COMPOSITE MATERIALS**
- **DATA OFTEN USED TO ESTABLISH PRELIMINARY DESIGN STRENGTH**

DATA OBTAINED:

- **IMPACT DAMAGE CHARACTERISTICS VERSUS IMPACT ENERGY**
- **COMPRESSION STRENGTH AFTER IMPACT**


COUPON LEVEL IMPACT TEST APPARATUS





PLY LEVEL IMPACT DAMAGE C-SCAN ANALYSIS

216



Turn 30 0 Tilt 30 0
0 10 20 30 40 50 60
2 File: IERPCB.INC created OCT 25,

ORIGINAL PAGE IS
OF POOR QUALITY



INTERNAL DAMAGE DUE TO IMPACT

HIGH STRAIN CELION/974
1/2 IN. DIA. IMPACTOR

48 PLY QUASI-ISOTROPIC LAMINATE

40 FT LB IMPACT



60 FT LB IMPACT




10X

10X



IMPACT RESPONSE - RESIN EFFECTS



7



2 NOMINAL THICKNESS IS
.250 IN. (REF).



ALL DIMENSIONS ARE IN INCH

NOTES:

C-8
IMPACTED COMPRESSION COUPON



COMPRESSION TEST FIXTURE AND SPECIMEN




CFR-18

ORIGINAL PAGE IS
OF POOR QUALITY



COMPRESSION AFTER IMPACT



DYNATUP IMPACT SYSTEM







222

ORIGINAL PAGE IS
OF POOR QUALITY



COMPARATIVE C-SCANS OF DYNATUP AND LOCKHEED IMPACT SYSTEMS





224

MICROGRAPHIC COMPARISON OF DYNATUP AND LOCKHEED SYSTEMS 960 IN. LBS./IN.



LOCKHEED



DYNATUP

ORIGINAL PAGE IS
OF POOR QUALITY



**MICROGRAPHIC COMPARISON OF DYNATUP
AND LOCKHEED SYSTEMS
1440 IN. LBS./IN.**

LOCKHEED

DYNATUP

225

ORIGINAL PAGE IS
OF POOR QUALITY



MICROGRAPHIC COMPARISON OF DYNATUP
AND LOCKHEED SYSTEMS
1920 IN. LBS./IN.



ORIGINAL PAGE IS
OF POOR QUALITY



**MICROGRAPHIC COMPARISON OF DYNATUP AND
LOCKHEED SYSTEMS
2880 IN. LBS./IN.**



DYNATUP

227


ORIGINAL PAGE IS
OF POOR QUALITY

CPA 9/8



228

**MICROGRAPHIC COMPARISON OF DYNATUP AND
LOCKHEED SYSTEMS
2880 IN. LBS./IN.**



LOCKHEED

**ORIGINAL PAGE IS
OF POOR QUALITY**

MICROGRAPHIC COMPARISON OF DYNATUP AND
LOCKHEED SYSTEMS
2880 IN. LBS./IN.

SUBCOMPONENT IMPACT TESTS

PURPOSE:

- **EVALUATION OF GEOMETRICAL DETAILS ON IMPACT DAMAGE TOLERANCE**
- **DETERMINATION OF ALLOWABLE DESIGN STRENGTH**


DATA OBTAINED:

- **IMPACT DAMAGE CHARACTERISTICS VERSUS PANEL CONFIGURATION AND IMPACT LOCATION**
- **STRENGTH AFTER IMPACT**



230

THREE STRINGER IMPACT TEST SETUP



ORIGINAL PAGE IS
OF POOR QUALITY

MICROSECTION OF DAMAGE DUE TO
IMPACT BETWEEN STRINGERS




THREE STRINGER PANEL STRENGTH
AFTER IMPACT TEST



232

THREE STRINGER PANEL STRENGTH AFTER IMPACT TEST




IMPACT BELT
WIND PROTECTION OF D


ORIGINAL PAGE IS
OF POOR QUALITY




AS4/1806 T STIFFENED PANELS



BASELINE



DISCRETE PAD-UP



INTEGRAL PAD-UP




TEE STIFFENED PANEL COMPRESSION TESTS **MATL: AS4/1806 TAPE PANEL WEIGHT: 0.034 LB/IN²**

	TEST CONFIGURATION	FAILURE LOAD (KIPS)	N _x (LB/IN) N _{xULT} = 22,000 LB/IN	FAILURE STRAIN (IN/IN)
BASELINE		499.8	35,200	0.0064
		488.5	34,400	0.0071
		495.0 ^① / 413.9 ^②	23,800 ^① / 19,900 ^②	0.0045 ^① / 0.0047 ^②
		499.2 ^① / 528.3 ^②	24,000 ^① / 25,400 ^②	0.0045 ^① / 0.0061 ^②
INTEGRAL PAD-UP		453.0	31,900	0.0056
		563.7	39,700	0.0068
DISCRETE PAD-UP		409.0	28,800	0.0049
		420.3	29,600	0.0050

① CENTER STIFFENER FAILURE ② RESIDUAL STRENGTH



AS4/1806 FABRIC J-STIFFENED DESIGN



$N_{xULT} = 22,000 \text{ LB/IN}$




J-STIFFENED PANEL COMPRESSION TESTS

MATL: AS4/1806 FABRIC

TEST CONFIGURATION	FAILURE LOAD (KIPS)	M_x (LB/IN) $M_{x_{ult}} =$ 22000 LB/IN	FAILURE STRAIN (IN/IN)
 0.25 DIA FASTENERS CRIPPLING	484.2	34100	0.0064
 COLUMN	329.7	27570	0.0045
 100 FT-LB POST-IMPACT	524.9	25240	0.0048
 60 FT-LB POST-IMPACT	541.3	26020	0.0046





IM7/8551-7 TAPE BLADE STIFFENED DESIGN





238


BLADE STIFFENED PANEL COMPRESSION TESTS
MATL: IM7/8551-7 TAPE PANEL WEIGHT: 0.027 LB/IN²

TEST CONFIGURATION	FAILURE LOAD (KIPS)	N _x (LB/IN) N _{xULT} = 22,000 LB/IN	FAILURE STRAIN (IN/IN)
 0.25 DIA FASTENERS CRIPPLING	282.1	25,880	0.0052
 POST-IMPACT 100 FT-LB	211.8	19,430	0.0036
 POST-IMPACT 100 FT-LB	373.2	23,550	0.0046
 POST-IMPACT 40 FT-LB	361.2	22,790	0.0044

7624-037
7-11-88




COMPARISON OF COUPON DATA TO BLADE STIFFENED PANEL DATE





240

BASELINE BLADE STIFFENED DESIGN



AS4/2220




7624-000
7-11-08

ORIGINAL PAGE IS
OF POOR QUALITY



DAMAGE TOLERANCE IMPROVEMENT CONCEPTS



'SOFT' LAMINATE WITH
ADHESIVE INTERLEAVE
 $\epsilon = 0.00450$ IN./IN.



0° INSERT

WITH INSERT $\epsilon = 0.00397$ IN./IN.
WITHOUT INSERT $\epsilon = 0.00528$ IN./IN.




ADHESIVE INTERLEAVE BETWEEN
0° & 45° PLYS
 $\epsilon = 0.0040$ IN./IN.




BASELINE
'HARD' SKIN
 $\epsilon = 0.00354$ IN./IN.



AS4/2220 COUPON AND BLADE STIFFENED PANEL DATA




SCHEMATIC OF 4-STRINGER PANEL TEST ARTICLE




All dimensions are in millimeters.

STATIC STRENGTH COMPARISON OF 4-STRINGER PANELS



SHEAR PANEL IMPACT DAMAGE STRENGTH TEST STATIC AND FATIGUE





245

ORIGINAL PAGE IS
OF POOR QUALITY



246

HIGH VELOCITY IMPACT TESTS



ORIGINAL PAGE IS
OF POOR QUALITY

COMPONENT IMPACT TESTS


PURPOSE:

- **VERIFICATION OF IMPACT DAMAGED STRENGTH**


DATA OBTAINED:

- **IMPACT DAMAGE CHARACTERISTICS**
- **STRENGTH AFTER IMPACT**

STIFFENED PANEL WITH CUT-OUT



STIFFENED PANEL WITH CUT-OUT IMPACT
DAMAGE STRENGTH TEST





250

PANEL TEST RESULTS

TEST CONDITION	COMPRESSION LOAD (LB/IN)	MAX. STRAIN (IN/IN)	FAR FIELD STRAIN (IN/IN)
UNDAMAGED	16100	0.0041	0.0020
DAMAGED - 2 SKIN IMPACTS AT 100 FT-LB - 1 BLADE IMPACT AT 30 FT-LB	23900	0.0066	0.0033

7834-000A
7-11-08

BOX BEAM COMPONENT

251

ORIGINAL PAGE IS
OF POOR QUALITY

BOX BEAM COMPONENT TEST SETUP



252




ORIGINAL PAGE IS
OF POOR QUALITY



FULL SCALE RUDDER TEST PROGRAM

I. STATIC / FATIGUE TEST

- TESTED TO DESIGN ULTIMATE LOADS NO VISIBLE DAMAGE
- SUBJECTED TO 2 LIFETIMES OF FATIGUE CYCLES



II. ACOUSTIC TEST

- SUBJECTED TO AN ACOUSTIC / THERMAL EQUIVALENT OF 2 LIFETIMES
 - NO VISIBLE DAMAGE
 - SOME DELIMITATIONS ALONG RISERS DISCOVERED AFTER ONE LIFETIME (POSSIBLY THERE SINGLE INITIAL MANUFACTURING). NO GROWTH OF DELAMS, HOWEVER, FROM 1 LIFETIME TO 2.

III. STATIC TEST 70 FAILURE

- RUDDER SURFACE IMPACTED 4 LOCATIONS
- FAILURE OCCURRED @ 125% OF DESIGN ULTIMATE BENDING MOMENT.

SUMMARY

- LAMINATE IMPACT TESTS ARE ADEQUATE TO DETERMINE RELATIVE IMPACT DAMAGE BEHAVIOR OF COMPOSITES.
- INDUSTRY STANDARD FOR COUPON IMPACT TESTS SHOULD BE ESTABLISHED.
- SUBCOMPONENT IMPACT TESTS ARE REQUIRED TO ESTABLISH GEOMETRICAL EFFECTS AND DESIGN SPECIFIC STRENGTH ALLOWABLES.
- COMPONENT IMPACT TESTS ARE REQUIRED TO VERIFY STRUCTURAL INTEGRITY.

IMPACT DAMAGED COMPOSITES, PART II: STANDARD TESTS FOR FUSELAGE STRUCTURAL ISSUES

Ernest F. Dost

and


William B. Avery

Boeing Commercial Airplane Group


Impact Damaged Composites, Part 1: Damage Simulation and Strength Predictions




Impact Damaged Composites, Part 2: Standard Tests for Fuselage Structural Issues



Objective: Identify Critical Impact Threats for Fuselage



Impact Designed Experiment Involving Multiple Variables

Material variables	Laminate variables	Structural variables	Extrinsic variables
 Fiber • AS4 • IM7 Resin • 938 (3501-6) • 977-2 Fiber volume • 0.480 • 0.565 Material form • Tape • Tow	 Stiffener layout • Hard • Soft Skin layout • Hard • Soft Thickness • Thick (approximately 0.2 in) • Thin (approximately 0.1 in)	 Stiffener type • Blade • Hat Stiffener spacing • 7 in • 12 in Stiffener adhesive layer • With • Without	 Impact mass • 0.5 lbm • 12.0 lbm Impact energy (skin/stiffener) • 80 in-lb/200 in-lb • 1,200 in-lb/2,000 in-lb Impact temperature • 70°F • 180°F Impact diameter • 0.25 in • 1.0 in Impactor tup shape • Flat • Spherical Impactor stiffness • 0.5 Msi • 30 Msi


NASA/BOEING
ATCAS

DL 4823.11 DR 1s


THE DESIGN OF EXPERIMENTS (DOE) TECHNIQUE

Example: Variables

No Interaction



Interaction



THE DESIGN of EXPERIMENTS (DOE) TECHNIQUE


Summary for 16 Variables

One Variable at a Time: 17 Tests


Fully Crossed Experiment: 65,536 Tests

Fractional Factorial: 32 Tests

Critical Impact Locations




- (1) Skin midbay
- (2) Edge of stiffener attachment flange
- (3) Base of stiffener web
- (4) Top of stiffener




NASA/BOEING
ATCAS

DL 8823.14 DR 19



High Velocity, Low Mass, Instrumented Tup



1 inch


total weight = 0.62 lbs

dynamic calibration factor = 1.65

UBC
Mar 14 1991

Force vs time


QUASIS at velocity 30.14 m/s and mass 0.252 Kg



IMPACT DAMAGE ZONE MEASURED RESPONSE VARIABLES

Overall Damage Geometry and Distribution

Fiber Damage



Matrix Damage



Planar View

Cross-sectional View



Through-Thickness
Unsymmetry



First Keel Design



A18228-14 D

1st Sandwich Impact Damage Resistance Designed Experiment

Variables Studied:


Facesheet Thickness
 Core Density
 Fabrication Sequence
 Facesheet Material

Run Number	Laminate Thickness	Core Density	Fabrication Sequence	Facesheet Material
1	0.045	110 WF	Precured Skin	IM7/938
2	0.045	110 WF	Cocured Skin	IM7/8551-7
3	0.045	200 WF	Cocured Skin	IM7/938
4	0.045	200 WF	Precured Skin	IM7/8551-7
5	0.134	200 WF	Precured Skin	IM7/938
6	0.134	200 WF	Cocured Skin	IM7/8551-7
7	0.134	110 WF	Cocured Skin	IM7/938
8	0.134	110 WF	Precured Skin	IM7/8551-7


Thru-Transmission Ultrasound - Signal Response Rohacell Foam Sandwich Panels

268


Sample Input Signal




Recieved Signals



500 KHZ




750 KHZ



1000 KHZ


IMPACT LOAD vs. DEFLECTION

Facesheet: IM7/8551-7, Thickness = .088 in. Core Density: 110 WF




06 07 08

250 MHz
10 dB gain caldata
30 dB gain preASE
300 MHz pp in ASE



0 10 20 30 40 50 60 70 80 90 100
Z File: M630491D.TMC created MON 4 1991 14:53:52

500 MHz
 10 4h Gain o
 20 3h Gain in
 30 2h Gain in
 40 1h Gain in
 50 0h Gain in H2O



0 10 20 30 40 50 60 70 80 90 100
 100 90 80 70 60 50 40 30 20 10 0
 100 90 80 70 60 50 40 30 20 10 0

ORIGINAL PAGE IS
 OF POOR QUALITY

5 MHZ Pulse-Echo Time of Flight C-Scans Rohacell Foam Sandwich Panels

Facesheet: IM7/938
Core Density: 13 lb/ft


Facesheet: IM7/8551-7
Core Density: 13 lb/ft



DOE1 5.2500

DOE1 4.2500

DOE1 6.2500



0 18 20 250 40 50 60 70 80 90 100
File: H0220910-IMG CREATED FEB 20, 1991 16:16:52

1-2-2213-8



ORIGINAL PAGE IS
OF POOR QUALITY

1-8-2008



ORIGINAL PAGE IS
OF POOR QUALITY


1-6-2006-4



ORIGINAL PAGE IS
OF POOR QUALITY


Eight Run DOE: 500 kHz TTU Results

Response Variable: Histogram Average Attenuation (db)




Eight Run DOE: Dynatup Impact Response

Response Variable: Peak Force




Eight Run DOE: Dynatup Impact Data

Response Variable: Dent Depth



Eight Run DOE: 500 KHZ Impact TTU Results

Response Variable: Damage Diameter



Impact Damage Resistance and Residual Strength of Sandwich Structure for Aircraft Fuselage

Variables

Core type: Foam versus honeycomb

Core density: 6 to 18 lb/ft³

Core thickness: 0.25 to 0.75 in

Face sheet thickness: 0.1 to 0.3 in

Fiber type: AS4 versus IM7

Matrix type: 3501-6 versus 8551-7

Impactor shape: Flat versus spherical

Impactor diameter: 0.25 to 1.0 in

Constant gauge



Tapered



Laminate layout: Hard versus soft

Fiber type: AS4 versus IM7

Matrix type: 938 versus 977-2


Fiber volume: 0.480 versus 0.565

Material form: Tow versus tape

Impact Damaged Composites, Part 1: Damage Simulation and Strength Predictions



Impact Damaged Composites, Part 2: Standard Tests for Fuselage Structural Issues



Standard Specimen Tests for Fuselage Applications

Part 2 Summary

OUTLINE

- **COMPRESSION AFTER IMPACT**
- **TENSION AFTER THROUGH PENETRATION**
- **COMPRESSION AFTER THROUGH PENETRATION**
- **OTHER MATERIAL SCREENING NEEDS**
- **SUMMARY**

COMPRESSION AFTER IMPACT

**ARE EXISTING SPECIMEN GEOMETRIES AND
STANDARD TEST PROCEDURES SUFFICIENT?**

YES, IF YOU UNDERSTAND:

- THE IMPACT INDUCED DAMAGE STATE
- SPECIMEN BUCKLING LIMITS
- FINITE WIDTH CORRECTION FACTORS
- IMPACTOR SIZE, SHAPE, WEIGHT, AND STIFFNESS EFFECTS
- CAI FAILURE MODES
- PLY THICKNESS AND STACKING SEQUENCE EFFECTS
- SUBLAMINATE STABILITY
- SPECIMEN CURVATURE EFFECTS
- ROLL OF UNDAMAGED COMPRESSION STRENGTH
- THE EFFECT OF STIFFENERS
- AND THE INTER-RELATIONSHIPS BETWEEN ALL OF THE ABOVE


NO / MAYBE, IF YOU INCLUDE:

- **COMPRESSION AFTER THROUGH PENETRATION**
- **SHEAR AFTER IMPACT**
- **COMBINED LOADING**
- **TAPERED THICKNESS**


IMPACT VARIABLES

- **STATIC INDENTATION VS. DROP WEIGHT VS. CONTROLLED VELOCITY**
 - RATE SENSITIVE MATERIALS?
 - DAMAGE STATE CHANGE WITH IMPACT RATE?
- **IMPACTOR VARIABLES**
 - **GEOMETRY (DIAMETER, SHAPE)**
DAMAGE STATE CHANGES WITH IMPACTOR DIAMETER
 - **MASS** } **LEAD**
 - **STIFFNESS** } **STEEL**
 - **STIFFNESS** } **NYLON**
- **RANGE OF IMPACT ENERGIES**
 - **NEED TO UNDERSTAND VISIBILITY AS A FUNCTION OF ENERGY**
 - **LOW ENERGY (SMALL DAMAGE) VS. HIGH ENERGY (LARGE DAMAGE)**
 - DAMAGE STATE CHANGES
 - FAILURE MECHANISMS CHANGE


Predictions and experimental results for 12.7 cm wide specimens, AS6/3501-6,(45/0/-45/90)_{5S}, and ply thickness = 0.0188 cm.




Impact Energy as a Function of
Damage Area



CAI Strength versus Damage Area



Theoretical damage tolerance curves for two material types.



NEED FOR ENHANCED DATA EVALUATION

- INSTRUMENTED IMPACT DATA
 - FORCE-TIME CURVES
 - FORCE-DISPLACEMENT CURVES
- DAMAGE CHARACTERIZATION
 - FIBER FAILURE VS. DELAMINATION
 - NDE TECHNIQUES: PULSE-ECHO TIME-OF-FLIGHT C-SCAN
- SUPPORTING ANALYSIS
 - SPECIMEN BUCKLING LIMITS
 - FINITE WIDTH EFFECTS VS. DAMAGE SIZE
- FAILURE MODE IDENTIFICATION

Example of Instrumented Impact Results and Application To Impact Modeling

292





Figure 10. Instrumented Impact Results for the Resin Content Study

Figure 11. Predicted and Experimental Results for a Specimen from Batch B4, Impacted at an Energy of 180 in-lb.

T800/3900-2

B1: Low Resin Content

B2: Intermediate Resin Content

B4: High Resin Content

Ref.: Dodd Grande, et al., "Effects of Intra- and Inter-Laminar Resin Content on the Mechanical Properties of Toughened Composite Materials," NASA Conference Publication 3104, pp. 455-476.





Figure 5. Finite specimen width effects for IM6/3501-6 moduli, (45W-45/90)_{NS} (n=3), undamaged compressive strength = 478 MPa, and ply thickness = 0.0188 cm.

MATERIAL, LAMINATE, AND STRUCTURAL VARIABLES

- **TOUGHNESS VS. BASIC COMPRESSION STRENGTH**
- **PLY THICKNESS AND LAMINATE STACKING SEQUENCE**
 - **EFFECT ON SPECIMEN STABILITY**
 - **EFFECT ON SUBLAMINATE STABILITY**
 - **EFFECT ON DAMAGE STATE**


Predictions of the effects of undamaged compressive strength for
 (45/0/-45/90)_{ns} ($n \geq 3$), IM6/3501-6 moduli, and ply thickness = 0.0188 cm.




SPECIMEN CURVATURE / SPECIMEN THICKNESS


- **INCREASED INTERLAMINAR SHEAR COMPONENT RESULTS IN LARGER DELAMINATIONS**
- **CURVATURE INCREASES SUBLAMINATE STABILITY**
- **RESULTS FOR HITEX-46/V398-G BMI LAMINATES**

CURVED CAI SPECIMEN




Damage Area vs. Energy
Gr/BMI (45/90/-45/0)3s






CAI Strength vs. Damage Area

Gr/BMI (45/90/-45/0)3s



CAI Strength vs. Impact Energy

Gr/BMI (45/90/-45/0)3s



RECOMMENDED CAI STRENGTH TEST EVALUATION SCHEMES

- **STUDY A RANGE OF IMPACT LEVELS.**
- **CONSIDER POSSIBLE EFFECTS OF IMPACTOR GEOMETRY, MASS AND VELOCITY.**
- **USE INSTRUMENTED IMPACT TEST METHODS TO QUANTIFY DAMAGE RESISTANCE.**
- **NONDESTRUCTIVELY MEASURE IMPACT DAMAGE SIZE PRIOR TO THE CAI TEST.**
- **ANALYTICALLY SCALE CAI RESULTS TO ELIMINATE FINITE SPECIMEN WIDTH EFFECTS.**
- **VALIDATE ANALYSIS WITH TEST RESULTS TO ADD CONFIDENCE IN USING THE MODELS TO EXTRAPOLATE THE DATA BASE.**
- **EXAMINE BROKEN SPECIMENS TO JUDGE FAILURE MODE FOLLOWING CAI TESTS.**

ELEMENT GEOMETRIES

1. CRIPPLING SPECIMENS

- **IMPACT DAMAGED IN STRUCTURAL CONFIGURATIONS**

2. SKIN/STRINGER SEPARATION

- **IMPACT DAMAGED IN STRUCTURAL CONFIGURATIONS**

TENSION AFTER THROUGH PENETRATION

BOEING CROWN STUDIES:


TEST METHOD


- 3.5" X 12" SPECIMEN
- 2.5" X 5" WINDOW IN SUPPORT FIXTURE
- 0.875" X 0.060" BLADE


IMPACT RESULTS

- THINNER SPECIMENS EXHIBIT FIBER DAMAGE
- THICKER SPECIMENS EXHIBIT EXTENSIVE DELAMINATION


Expanded View of Blade Impacter








ASG-2367 bw




308

ORIGINAL PAGE IS
OF POOR QUALITY

SPLATE Simulation of Blade Impact AS4/938 Force-Time Data



SPLATE Simulation of Blade Impact AS4/938 Displacement Curves




TENSION RESIDUAL STRENGTH

• FOR THICKER SPECIMENS RESIDUAL STRENGTH OF PENETRATION SPECIMENS IS GREATER THAN SLIT SPECIMENS

• FOR THINNER SPECIMENS RESIDUAL STRENGTHS APPROXIMATELY EQUAL OR SLIGHTLY LESS

Comparison of Slit and Penetration Strengths Material = IM6/3501-6, w/d = 4, w = 3.5



For Each notch type: penetration slit

HYPOTHESIS

- IN THICK LAMINATES THE PENETRATION EVENT CAUSES PRIMARILY DELAMINATIONS BEYOND THE PENETRATION, WHICH SOFTENS THE NOTCH TIP REGION AND THEREFORE INCREASES STRENGTH
- IN THINNER LAMINATES THE PENETRATION CAUSES FIBER BREAKAGE BEYOND THE PENETRATION, WHICH INCREASES THE EFFECTIVE NOTCH LENGTH AND REDUCES STRENGTH

RECOMMENDED STANDARD COUPON

SPECIMEN: 3.5" X 12"
CUT-OUT: 2.5" X 5"
IMPACTOR: 0.875" X 0.060"

ENGINEERING EVALUATION NEEDED

- LARGE DEFLECTIONS
- NON-LINEAR EFFECTS
- SPECIMEN THICKNESS EFFECTS
- CUT-OUT SIZE EFFECTS

ALL RELATED

OTHER MATERIAL SCREENING NEEDS

- 1. COMPRESSION AFTER THROUGH PENETRATION**
- 2. SHEAR STRENGTH AFTER IMPACT**
- 3. COMBINED LOAD REDISTRIBUTION**
 - COMPRESSION / SHEAR
 - COMPRESSION / HOOP TENSION
 - IMPACT AND THROUGH PENETRATION
- 4. SANDWICH SPECIMEN GEOMETRIES**
 - 5"X10" WITH 4"X4" CUT-OUT IN SUPPORT FIXTURE

Impact Damaged Composites: Summary for Parts 1 and 2

Critical Impact Threats for Fuselage Structure Must Be Identified

**Accurate Predictions of Post-Impact Strength Require
Characterization of Important Damage Features**

**Complex Damage States Must be Simulated (e.g., Sublaminar Buckling Approach)
to Allow Engineering Analysis of Structural Configurations**

**The Post-Impact Strength/Damage Relationships for Fuselage Structure Will
Depend on Location, Combined Load States, and Load Redistribution**

**Fundamentals Must be Understood to Relate Coupon Screening Tests
to Fuselage Structural Performance**

References Giving More Information on Topics Covered

- 1.) Gosses, J.H., Mori, P.B.Y., "Impact Damage Characterization of Graphite/Epoxy Laminates," In Proc. of 3rd Tech Conf. of American Society for Composites, Technomic Publ. Co., 1988, pp. 344-353.
- 2.) Dost, E.F., Ikoniecz, L.B., Gosses, J.H., "Sublaminar Stability Based Modeling of Impact Damaged Composite Laminates," In Proc. of 3rd Tech. Conf. of Society for Composites, Technomic Publ. Co., 1988, pp. 354-363.
- 3.) Ikoniecz, L.B., Dost, E.F., Coggeshall, R.L., "A Model for Compression After Impact Strength Evaluation," In Proc. of 21st Inter. SAMPE Tech. Conf., Soc. for Adv. of Material and Process Engineering, 1989, pp. 130-140.
- 4.) Avery, W.B., "A Semi-Discrete Approach to Modeling Post-Impact Compression Strength of Composite Laminates," In Proc. of 21st Inter. SAMPE Tech. Conf., Soc. for Adv. of Material and Process Engineering, 1989, pp. 141-151.
- 5.) Dost, E.F., Ikoniecz, L.B., Avery, W.B., Coxon, B.R., "The Effects of Stacking Sequence On Impact Damage Resistance and Residual Strength for Quasi-Isotropic Laminates," In Composite Materials: Fatigue and Fracture, ASTM STP 1110, 1991.
- 6.) Avery, W.B., Grande, D.H., "Influence of Materials and Layout Parameters On Impact Damage Mechanisms," In Proc. of 22nd Inter. SAMPE Tech. Conf., Soc. for Adv. of Material and Process Engineering, 1990, pp. 470-483.
- 7.) Grande, D.H., Ikoniecz, L.B., Avery, W.B., Bascom, W.D., "Effects of Intra- and Inter-Laminar Resin Content On Mechanical Properties of Toughened Composite Materials," In Proc. of First NASA Advanced Composite Technology Conf. (Part 2), 1990, pp. 465-475.
- 8.) Dost, E.F., Avery, W.B., Swanson, G.D., Lin, K.Y., "Developments in Impact Damage Modeling for Laminated Composite Structures," In Proc. of First NASA Advanced Composite Technology Conf. (Part 2), 1990, pp. 721-738.

IMPACT DAMAGE RESISTANCE


and

MATERIAL TOUGHNESS

JOHN E. MASTERS
LOCKHEED ENGINEERING AND SCIENCE



DAMAGE SIZE vs. RESIDUAL COMPRESSION STRENGTH (Single Resin Systems)




COMPRESSION STRENGTH AFTER IMPACT

vs.

STRAIN ENERGY RELEASE RATE


(Single Resin Systems)




COMPRESSION STRENGTH AFTER IMPACT

vs.


STRAIN ENERGY RELEASE RATE (Thermoset-Thermoplastic Blends BASF)




IMPACT DAMAGE SIZE vs. STRAIN ENERGY RELEASE RATE (Single Resin Systems)



MODE I vs. MODE II STRAIN ENERGY RELEASE RATES (Single Resin Systems)




MODE I vs. MODE II STRAIN ENERGY RELEASE RATES (Single Resin and Interleafed Systems)




COMPRESSION STRENGTH AFTER IMPACT

VS.


STRAIN ENERGY RELEASE RATE (Single Resins and Interleafed Laminates)




COMPRESSION STRENGTH AFTER IMPACT VS. MODE I STRAIN ENERGY RELEASE RATE




DAMAGE SIZE vs. STRAIN ENERGY RELEASE RATE (Single Resins and Interleafed Laminates)




DAMAGE SIZE vs. RESIDUAL COMPRESSION STRENGTH (Single Resin and Interleafed Laminates)



DAMAGE SIZE vs. IMPACT FORCE **(AS4/3501-6 and IM7/8551-7)**



DAMAGE SIZE vs. RESIDUAL COMPRESSION STRENGTH
(AS4/3501-6 and IM7/8551-7)



SUMMARY:

Residual Compression Strength after Impact is a combined measure of

Material Resistance to Impact-Induced Delamination

Material Tolerance to Damage Propagation under Load

Impact Resistance is Directly Proportional to Material Toughness

Strong Correlation between Mode II Strain Energy Release Rate and Impact Resistance (Measured by Impact Delamination Size)

Material Tolerance to Impact Damage Insensitive to Toughness for a given Flaw Size

STANDARD IMPACT TESTS

**PRESENTED AT
NASA WORKSHOP ON IMPACT DAMAGE TO COMPOSITES**

**NASA LARC
MARCH 20, 1991**

**BY
DR. VICTOR L. CHEN
PRINCIPAL ENGINEER
COMPOSITES R&D
DOUGLAS AIRCRAFT COMPANY**

UNIVERSITY MICROFILMS
SERIALS ACQUISITION
300 N ZEEB RD
ANN ARBOR MI 48106-1500

FROM 50 2801
PAGE 0001

STANDARD IMPACT TESTS

COMPRESSION AFTER IMPACT

NASA ST-1

ST-1 SET-UP

SRM 2-88 (SACMA)

RECEIVED FROM THE IMPACT CENTER

TESTED BY

2000000 1000000 1000000

NASA ST-1

[+45/0/-45/90]_{NS} , 12" X 7" X 1/4"

10 LB. 1/2" HEMISPHERICAL STEEL TIP

NOMINAL 20 FT-LB IMPACT

REPLICA OF THREE

SACMA RECOMMENDED METHOD 2-88**[+45/0/-45/90]_{NS} , 6" X 4" X 1"****11 LB 5/8" HEMISPHERICAL STEEL TIP****1500 IN-LB/IN IMPACT**

COMPRESSION AFTER IMPACT TEST

ID	SPECIMEN SIZE	NO. OF PLIES	IMPACT ENERGY FT-LBS.	IMPACT IN-LB/IN THICK	DAMAGE SIZE AREA IN/SQ IN	COMPRESSION STRENGTH KSI	FAILURE STRAIN %	REMARKS
31	2.5x10	32	CONTROL	--	--	76.6	1.33	0.178 INCH
41	2.5x10	48	CONTROL	--	--	91.8	1.71	0.266 INCH
34	NASA ST-1	32	14.2	957	1.43 1.71	31.3	0.47	
44	ST-1	48	21.3	958	1.46 1.83	32.8	0.50	TUP DIA=0.5IN
37	ST-1	32	22.0	1486	1.25 1.35	29.2	0.44	
47	ST-1	48	33.2	1501	2.10 3.5	26.9	0.40	
310	4x6	32	22.0	1488	1.28 2.4	27.7	0.42	
410	4x6	48	33.3	1499	2.53 4.8	25.6	0.39	

MAT: AS4/8552 LAMINATE: (0, 45, 90, -45)_{NS}

ISSUES ON COMPRESSION AFTER IMPACT TEST

o IMPACT ENERGY OR IMPACT ENERGY/THICKNESS

o IMPACTOR SIZE

o SPECIMEN SIZE, THICKNESS

o OTHER VARIATIONS - DYNAMIC IMPACT PRELOADING MULTIPLE IMPACT

COMPRESSION AFTER IMPACT TEST




FIG. 12—Stress output locations for Figs. 14 to 22.




FIG. 14—Transverse shear stress distribution in a $(90^\circ/0^\circ/90^\circ)$ lay-up at 10 μs .




FIG. 18—Effect of contact area on shear stress distribution of a $[90/0/90]$ laminate.




Fig. 2 Effect of initial stresses on the residual strength.

CAI OF STIFFENED PANELS


○ **IMPACT SITES**

○ **SUPPORT DURING IMPACT**

○ **AUXILIARY TESTS - PEEL MOMENT TEST
PULL-OFF INTERACTION TEST
STIFFENER CRIMPING TEST**

B, C, ETC. = PANEL NUMBERS
= IMPACT SITES
12, 13 = STRAIN GAGE LOCATIONS

STRAIN GAGE AND IMPACT LOCATIONS ON PANELS



1,2...12 = STRAIN GAGE LOCATIONS
 ↓ = IMPACT SITES
 B₁ C₁, ETC. = PANEL NUMBERS






Figure 3. Support Conditions for Impact Tests



TEST RESULTS				
PANEL TYPE	TEST	N	P (LB)	M _p = 0.215 P N-mm (IN.-LBMM)
IV	1	7,794	(1,759)	1.67 (376)
	2	7,473	(1,669)	1.61 (361)
	3	7,673	(1,725)	1.65 (371)
	AVERAGE			1.64 (366)
V	1	9,340	(2,100)	2.01 (451)
	2	9,674	(2,175)	2.06 (467)
	3	9,452	(2,125)	2.03 (457)
	AVERAGE			2.04 (458)

Figure 4. Peel Moment Test



TEST RESULTS				
PANEL TYPE	TEST	RUNNING P N/mm (LB/IN.)	M _p = (P/2) (9.9 mm) N-m/mm (IN.-LB/IN.)	
VI	1	144 (825)	0.72	(161)
	2	177 (1,008)	0.66	(197)
	3	137 (785)	0.66	(153)
AVERAGE			0.76	(170)
ADJUSTED DATA TO ACCOUNT FOR 3-DEG MISALIGNMENT				
VI	1	194 (1,105)	0.92	(207)
	2	239 (1,362)	1.09	(245)
	3	185 (1,058)	1.02	(229)
AVERAGE			1.01	(227)

Figure 5. Pull-Off Interaction Test

INTERNAL LOAD	EFFECT OF A UNIFORMLY STIFF FLANGE	EFFECT OF A UNIFORMLY FLEXIBLE FLANGE
PULL-OFF LOAD 	 HIGH INTERLAMINAR TENSION UNDER BLADE AND AT FLANGE EDGE	 HIGHER INTERLAMINAR TENSION UNDER BLADE; REDUCED TENSION AT EDGE
PEEL MOMENT 	 HIGH INTERLAMINAR TENSION AT FLANGE EDGE	 REDUCED INTERLAMINAR TENSION AT FLANGE EDGE, SINCE FLEXIBLE FLANGE ATTRACTS LESS LOAD
BLADE MOMENT 	 HIGH INTERLAMINAR RADIAL TENSION IN THE ELBOW	 SIMILAR RESPONSE CAUSING RADIAL ELBOW TENSION

Figure 6. Effects of Internal Loads on Bonded Stringer Interlaminar Tension Stresses

TABLE 3
RESIDUAL COMPRESSION STRENGTH OF POSTIMPACT STIFFENED PANELS

PANEL ID	MATERIAL	LENGTH, WIDTH (IN.)	THICKNESS SKIN, FLANGE (NO. OF PLYS)	IMPACT LOCATION	IMPACT ENERGY J (FT-LB)	FAILURE STRESS (MPa (KSI))	FAILURE STRAIN (PERCENT)	NO. OF STIFFENERS
1	T700/3820	40 (15.75) 39 (15.4)	18, 9	MID-STRINGER	4.3 (3.21)	—	0.385	3, HAT
2	T700/3820	40 (15.75) 39 (15.4)	18, 8	STRINGER EDGE	4 (3.06)	—	0.385	3, HAT
3	T700/3820	40 (15.75) 39 (15.4)	18, 9	MIDBAY	4.2 (3.15)	—	0.494	3, HAT
4	T700/3820	40 (15.75) 39 (15.4)	18, 9	STRINGER EDGE	12.36 (9.09)	—	0.298	3, HAT
5	CARBON/ EPOXY TAPE	51 (20) 34.3 (13.5)	41, 41	MIDBAY	12.2 (9.0)	—	0.52	3, BLADE ADHESIVELY BONDED
6	CARBON/ EPOXY	48.1 (18.9) 38.6 (14.4)	41, 41	MIDBAY	14.2 (10.51)	—	0.37	3, BLADE ADHESIVELY BONDED
7	CARBON/ EPOXY	48.8 (18.9) 57.2 (22.5)	48, 48	MID-STRINGER	13.4 (9.87)	—	0.47	3, HAT
8	AS4/3501-6	81 (24) 45.7 (18)	48, 24	MIDBAY, MID-STRINGER, STRINGER EDGE	135.5 (100) EACH	—	0.37	3, CHANNEL MECHANICALLY FASTENED
9	AS4/3501-6	81 (24) 45.7 (18)	48, 24	MIDBAY	135.5 (100)	—	0.38	3, CHANNEL MECHANICALLY FASTENED
10	AS4/3501-6	81 (24) 45.7 (18)	48, 24	MIDBAY, MID-STRINGER, STRINGER EDGE	112.5 (83) EACH	—	0.38	3, CHANNEL MECHANICALLY FASTENED
11	AS4/3501-6	81 (24) 45.7 (18)	48, 24	CENTERS OF TWO BAYS	81.3 (60) EACH	—	0.32	3, CHANNEL MECHANICALLY FASTENED
12	AS4/3501-6	81 (24) 45.7 (18)	48, 24	CENTERS OF TWO BAYS	14.2 (40)	—	0.35	3, CHANNEL MECHANICALLY FASTENED
13	AS8/5245-6	81 (24) 45.7 (18)	48, 24	MIDBAY, MID-STRINGER, STRINGER EDGE	135.5 (100) EACH	—	0.39	3, CHANNEL MECHANICALLY FASTENED
14	IM6/180B	51 (20) 48 (19)	38, 14	MIDBAY	135.5 (100)	290 (42.3)	—	3, BLADE
15	IM6/180B	51 (20) 48 (19)	54, 14	MIDBAY	135.5 (100)	361 (52.3)	—	3, BLADE A-BONDED
16	IM6/180B	51 (20) 48 (19)	66, 14	MIDBAY	135.5 (100)	477 (69.1)	—	3, BLADE A-BONDED
17	IM6/180B	51 (20) 48 (19)	40, 14	MIDBAY	135.5 (100)	271 (39.3)	—	3, BLADE A-BONDED
18	IM6/180B	51 (20) 48 (19)	54, 38	MIDBAY	135.5 (100)	225 (32.8)	0.433	3, BLADE A-BONDED
19	IM6/180B	51 (20) 48 (19)	54, 38	MID-STRINGER	135.5 (100)	267 (38)	0.400	3, BLADE A-BONDED
20	IM6/180B	51 (20) 48 (19)	54, 18	MID-STRINGER	135.5 (100)	321 (46.5)	0.50	3, BLADE A-BONDED
21	IM6/180B	51 (20) 48 (19)	54, 18	MIDBAY	135.5 (100)	367 (53)	—	3, BLADE A-BONDED
22	IM6/180B	51 (20) 48 (19)	54, 18	MID-STRINGER	135.5 (100)	323 (47)	0.444	3, BLADE A-BONDED
23	IM6/180B	51 (20) 48 (19)	54, 18	MIDBAY	271 (100)	184 (26.7)	0.333	3, BLADE A-BONDED
24	IM6/180B	51 (20) 48 (19)	54, 18	SIDE OF BLADE	144 (108)	425 (61.7)	0.689	3, BLADE A-BONDED
25	IM7/8551-7	51 (20) 48 (19)	63, 18	MIDBAY	135.5 (100)	302 (43.8)	—	3, BLADE A-BONDED
26	IM7/8551-7	51 (20) 48 (19)	63, 18	MIDBAY	135.5 (100)	328 (47.3)	—	3, BLADE A-BONDED
27	IM6/180B	142 (56) 84 (33)	54, 18	MIDBAY	135.5 (100)	—	0.410	3, BLADE A-BONDED
28	IM6/180B	142 (56) 84 (33)	54, 18	MIDBAY	135.5 (100)	—	0.424	3, BLADE A-BONDED

WHY IMPACT TEST?

- DAMAGE TOLERANCE CRITERIA
- TYPE OF (IN-SERVICE) DAMAGE
- DAMAGE RESISTANCE
- COMPRESSION AFTER IMPACT TEST

TABLE 2
RESIDUAL COMPRESSION STRENGTH OF POSTIMPACT STEVEDO PANELS

TEST NO.	TEST DATE	TEST LOCATION	TEST TYPE	TEST RESULT	TEST COMMENT
1	10/1/77	101	101	101	101
2	10/1/77	102	102	102	102
3	10/1/77	103	103	103	103
4	10/1/77	104	104	104	104
5	10/1/77	105	105	105	105
6	10/1/77	106	106	106	106
7	10/1/77	107	107	107	107
8	10/1/77	108	108	108	108
9	10/1/77	109	109	109	109
10	10/1/77	110	110	110	110
11	10/1/77	111	111	111	111
12	10/1/77	112	112	112	112
13	10/1/77	113	113	113	113
14	10/1/77	114	114	114	114
15	10/1/77	115	115	115	115
16	10/1/77	116	116	116	116
17	10/1/77	117	117	117	117
18	10/1/77	118	118	118	118
19	10/1/77	119	119	119	119
20	10/1/77	120	120	120	120
21	10/1/77	121	121	121	121
22	10/1/77	122	122	122	122
23	10/1/77	123	123	123	123
24	10/1/77	124	124	124	124
25	10/1/77	125	125	125	125
26	10/1/77	126	126	126	126
27	10/1/77	127	127	127	127
28	10/1/77	128	128	128	128
29	10/1/77	129	129	129	129
30	10/1/77	130	130	130	130
31	10/1/77	131	131	131	131
32	10/1/77	132	132	132	132
33	10/1/77	133	133	133	133
34	10/1/77	134	134	134	134
35	10/1/77	135	135	135	135
36	10/1/77	136	136	136	136
37	10/1/77	137	137	137	137
38	10/1/77	138	138	138	138
39	10/1/77	139	139	139	139
40	10/1/77	140	140	140	140
41	10/1/77	141	141	141	141
42	10/1/77	142	142	142	142
43	10/1/77	143	143	143	143
44	10/1/77	144	144	144	144
45	10/1/77	145	145	145	145
46	10/1/77	146	146	146	146
47	10/1/77	147	147	147	147
48	10/1/77	148	148	148	148
49	10/1/77	149	149	149	149
50	10/1/77	150	150	150	150
51	10/1/77	151	151	151	151
52	10/1/77	152	152	152	152
53	10/1/77	153	153	153	153
54	10/1/77	154	154	154	154
55	10/1/77	155	155	155	155
56	10/1/77	156	156	156	156
57	10/1/77	157	157	157	157
58	10/1/77	158	158	158	158
59	10/1/77	159	159	159	159
60	10/1/77	160	160	160	160
61	10/1/77	161	161	161	161
62	10/1/77	162	162	162	162
63	10/1/77	163	163	163	163
64	10/1/77	164	164	164	164
65	10/1/77	165	165	165	165
66	10/1/77	166	166	166	166
67	10/1/77	167	167	167	167
68	10/1/77	168	168	168	168
69	10/1/77	169	169	169	169
70	10/1/77	170	170	170	170
71	10/1/77	171	171	171	171
72	10/1/77	172	172	172	172
73	10/1/77	173	173	173	173
74	10/1/77	174	174	174	174
75	10/1/77	175	175	175	175
76	10/1/77	176	176	176	176
77	10/1/77	177	177	177	177
78	10/1/77	178	178	178	178
79	10/1/77	179	179	179	179
80	10/1/77	180	180	180	180
81	10/1/77	181	181	181	181
82	10/1/77	182	182	182	182
83	10/1/77	183	183	183	183
84	10/1/77	184	184	184	184
85	10/1/77	185	185	185	185
86	10/1/77	186	186	186	186
87	10/1/77	187	187	187	187
88	10/1/77	188	188	188	188
89	10/1/77	189	189	189	189
90	10/1/77	190	190	190	190
91	10/1/77	191	191	191	191
92	10/1/77	192	192	192	192
93	10/1/77	193	193	193	193
94	10/1/77	194	194	194	194
95	10/1/77	195	195	195	195
96	10/1/77	196	196	196	196
97	10/1/77	197	197	197	197
98	10/1/77	198	198	198	198
99	10/1/77	199	199	199	199
100	10/1/77	200	200	200	200

PRELIMINARY DAMAGE TOLERANCE CRITERIA

Flaw / Damage Type	Flaw / Damage Size (1)
Scratches	Assume the presence of a surface scratch that is 4.0 in long and 0.02 in deep
Delamination	Assume the presence of an interply delamination that has an area equivalent to a 2.0-in diameter circle with dimensions most critical to its location (2)
Impact Damage	Assume the presence of damage caused by the impact of a 1.0-in diameter hemispherical impactor with 100 ft-lb of kinetic energy or with that kinetic energy required to cause a dent 0.10 in deep, whichever is least

- (1) For limited access areas such as the interior of the wing, the contractor shall have the option of proposing an inspection procedure before closeout which will allow the assumed damage area size to be reduced
- (2) This requirement also accounts for delamination that might occur and be nondetected as a result of in-service repair

the following information:

(1) The following information is required for the purpose of the following:

(a) The following information is required for the purpose of the following:

(b) The following information is required for the purpose of the following:

(c) The following information is required for the purpose of the following:

IMPACT DAMAGE

Matrix cracking
Transverse shear crack
Bending (tension) crack

Delamination
Fiber breakage

(THROUGH-THE-THICKNESS CRACK)

Matrix cracking Transverse shear crack Bending (tension) crack	Matrix cracking Transverse shear crack Bending (tension) crack
Delamination Fiber breakage	Delamination Fiber breakage
(THROUGH-THE-THICKNESS CRACK)	(THROUGH-THE-THICKNESS CRACK)




FIG. 1—Nomenclature of damage modes. (a) Longitudinal section. (b) Transverse section.



Mechanism 1: Tension, no delamination or shear



Mechanism 2: Tension and shear, tension dominated



Mechanism 3: Tension and shear, shear dominated



Mechanism 4: Shear, small amounts of tension

Figure 1. Fracture Mechanisms

DAMAGE RESISTANCE

IMPACT DAMAGE =

F (STACKING SEQUENCE, IMPACT ENERGY)

- o SPECIMEN SUPPORT**
- o IMPACT FORCE**
- o CONTACT STRESS DISTRIBUTION**

DAMAGE TOLERANCE**CAI STRENGTH**

$$= F \left(\frac{\text{DAMAGE SIZE}}{\text{SPECIMEN SIZE}} \right)$$


- o WHAT KIND OF DAMAGE
- o SHOULD WE CONSIDER TAI
SAI



STRUCTURAL MECHANICS

Douglas Aircraft
NAS 1-100012

WHAT IS RESIDUAL STRENGTH






358

STRUCTURAL MECHANICS

Douglas Aircraft
NAS-1-10002

RESIDUAL STRENGTH PREDICTION DEVELOPMENT



CAI

STIFFENER PULL-OFF

DAMAGED STIFFENED
PANEL COMPRESSION TEST

ANALYSIS

- DAMAGE MODELING (REDUCED STIFFNESS AND STRENGTH)
- ULTIMATE STRENGTH PREDICTION ON DAMAGE PARTS (FINITE ELEMENT ANALYSIS WITH PARAMETERS OBTAINED FROM DAMAGE MODEL)


358



RESIN PROPERTIES

Douglas Aircraft
NAS1-18862

Douglas Resin Selection



**RELEVANCE OF IMPACTER
SHAPE TO TENSION STRENGTH
OF THICK CARBON/EPOXY WITH
NONVISIBLE DAMAGE**

C. C. Poe, Jr.

NASA Langley Research Center

NASA Workshop on Impact Damage to Composites

NASA Langley Research Center

Hampton, Virginia

March 19 & 20, 1991

OBJECTIVE

PRESENT METHOD TO PREDICT TENSION STRENGTH
WITH BARELY VISIBLE IMPACT DAMAGE --
IRRESPECTIVE OF IMPACTER SHAPE




Figure 1.- Space shuttle solid rocket motor.


ORIGINAL PAGE IS
OF POOR QUALITY

OUTLINE


**PART I - DAMAGE FROM SIMULATED IMPACTS
USING HEMISPHERICAL INDENTERS --
ANALYSIS & EXPERIMENTS**

**PART II - STRENGTH AFTER LOW-VELOCITY
IMPACTS -- ANALYSIS & EXPERIMENTS**

TEST SPECIMEN AND APPARATUS




SEM PHOTOGRAPHS OF DAMAGE 5.08-cm-dia Indenter With 589 MPa Pressure




DAMAGED LAYERS

127 cm dia. hole in wall 11.7 m from top of wall




DAMAGED LAYERS

2.54-cm-dia. indenter and 66.7-lb contact force




DAMAGED LAYERS 1-9

5.08-cm-dia. indenter and 267-kN contact force




DAMAGED LAYERS 10-18

5.08-cm-dia. indenter and 267-kN contact force



MAGNIFIED IMPACT DAMAGE IN 7TH LAYER


2.54-CM-INDENTER AND 54.3-KN IMPACT FORCE




0.076 mm

2.5 mm

VISIBILITY OF SURFACE DAMAGE



FIBER BREAK PROFILES FROM INDENTATION TESTS



ANALYTICAL APPROACH

- CALCULATE CONTACT STRESSES USING A. E. H. LOVE'S SOLUTION FOR HEMISPHERICAL PRESSURE APPLIED TO ISOTROPIC, SEMI-INFINITE BODY.
- CALCULATE DAMAGE SIZE USING MAXIMUM STRESS CRITERIA.

HERTZ LAW

FOR TRANSVERSELY ISOTROPIC BODIES -

Indentation.-

$$u = R_i^{-1/3} (P/n_o)^{2/3}$$

Pressure.-


$$p_c = (n_o/R_i)^{2/3} p^{1/3} / \pi$$

Contact radius.-


$$r_c = (PR_i/n_o)^{1/3} \\ = \pi P_c R_i / n_o$$

where


- $n_o = 4.52$ GPa from indentation measurements
- $= 4.69$ GPa from elastic constants
- $= 3.98$ GPa from contact radii measurements (previous investigation)




FAILURE UNDER COMPRESSION AND HYDROSTATIC PRESSURE




COMPRESSION TEST FOR SHEAR STRENGTH



EFFECT OF IMPACTER RADIUS ON DAMAGE DEPTH IN DEPLIED LAYERS



MAXIMUM STRESS CONTOURS - LOVE'S SOLUTION




CONCLUSIONS

- FIBERS BROKE BELOW CONTACT SITE AT CRITICAL CONTACT PRESSURE, INDEPENDENT OF INDENTER RADIUS.
- DAMAGE VISIBLE WHEN CRITICAL CONTACT PRESSURE WAS EXCEEDED.
- SIZE OF DAMAGE INCREASED WITH INCREASING CONTACT PRESSURE AND INDENTER RADIUS.
- SIZE OF DAMAGE WAS PREDICTED USING THEORY OF ELASTICITY AND MAXIMUM SHEAR STRESS CRITERIA.


PART II

STRENGTH AFTER LOW-VELOCITY IMPACTS -- ANALYSIS & EXPERIMENTS

IMPACT TESTS




ORIGINAL PAGE
BLACK AND WHITE PHOTOGRAPH



NASA
L-84-5453

EXPERIMENTAL APPROACH -- RESIDUAL STRENGTH TESTS



ANALYTICAL APPROACH

IMPACT FORCE — ENERGY BALANCE ANALYSIS



$$0.4 R_1^{-1/3} n_0^{-2/3} F_{max}^{2/3} + 0.6 k_b^{-1} F_{max}^2 - KE_{eff} = 0$$

WHERE

$$K_{eff} = M v_1^2 / 2$$


AND

$$M = 1 / [1/m_1 + 1/(m_2/4)]$$




STRENGTH — ANALYSIS OF SURFACE CRACKS

STRESS INTENSITY FACTOR FOR ISOTROPIC PLATE




EFFECT OF IMPACTER SHAPE ON IMPACT FORCE




COMPARISON OF DETECTABLE IMPACT DAMAGE

25.4-mm-DIA. IMPACTER




IMPRESSION DEPTHS FOR FWC

25.4-mm-DIA. IMPACTER




IMPACT FORCES FOR RINGS AND FWC

25.4-mm-DIA. HEMISPHERE INDENTER




IMPACT FORCE VERSUS EFFECTIVE KINETIC ENERGY

25.4-mm-DIA. HEMISPHERE INDENTER



EFFECT OF MASS & VELOCITY ON IMPACT FORCE

25.4-mm-DIA. HEMISPHERE INDENTER



IMPACT TESTS -

☐ **EMPTY**

■ FAILED


**NONVISIBLE
DAMAGE**

**CALCULATED FOR
INDENTATION ONLY**

**CALCULATED FOR
INDENTATION
AND BEAM FLEXURE**


40 60 100
KINETIC ENERGY, $m_1 v_1^2/2$, J

RADIOGRAPHS OF IMPACT DAMAGE FOR VARIOUS INDENTERS




ORIGINAL PAGE IS
OF POOR QUALITY


STRENGTH REDUCTION FACTOR VERSUS IMPACTER DIAMETER



STRENGTH REDUCTION FACTOR FOR NONVISIBLE DAMAGE CRITERIA




TENSION STRENGTH FOR HEMISPHERE INDENTERS




$$M = \sqrt{1/m_1 + 1/m_2/4}$$

STRENGTHS WITH SURFACE CUTS

$$c/a = 1.0$$




TWO-PART FAILURE WITH SURFACE DAMAGE



BEFORE FAILURE




FIRST-LIGAMENT FAILURE



REMAINING-LIGAMENT FAILURE

EFFECT OF IMPACTER SHAPE ON DAMAGE DEPTH IN RADIOGRAPHS



CONCLUSIONS

- IMPACT FORCE AND IMPACT PARAMETERS WERE CORRELATED QUITE WELL WITH AN ENERGY BALANCE ANALYSIS EXCEPT WHEN DAMAGE WAS EXTENSIVE.
- SURFACE CRACK ANALYSIS GAVE GOOD PREDICTIONS OF TENSION STRENGTHS.
- FOR BARELY VISIBLE DAMAGE --
 1. STRENGTHS WERE LOWER FOR BLUNT IMPACTERS THAN FOR SHARP IMPACTERS
 2. FACTOR OF SAFETY WAS INDEPENDENT OF IMPACTER SHAPE.

CERTIFICATION OF COMPOSITES FOR AIRCRAFT

John Lincoln

Aeronautical Systems Division,
Wright-Patterson Air Force Base

401

PRECEDING PAGE BLANK NOT FILMED



PRECEDING PAGE NOT 402

CERTIFICATION OF COMPOSITES FOR AIRCRAFT



BASIS FOR USAF AIRCRAFT

- MIL-STD-1530A THE USAF AIRCRAFT STRUCTURAL INTEGRITY PROGRAM (ASIP)

- PROGRAM FOR FULL SCALE DEVELOPMENT OF METAL AND COMPOSITE STRUCTURE

- COMPOSITE STRUCTURES CAUSE SOME SHIFTING OF EMPHASIS IN THE

TASKS OF ASIP

I DESIGN INFORMATION

II DESIGN ANALYSES AND DEVELOPMENT TESTS

III FULL SCALE TESTING

IV FORCE MANAGEMENT DATA PACKAGE

V FORCE MANGEMENT



TASK II

**MATERIALS AND
JOINT ALLOWABLES**




B-BASIS

**DERIVED FROM SUITABLE COUPONS WITH ENVIRONMENTAL
CONDITIONING-END OF LIFE MOSITURE CONDITION WITH
SEVERE BASING SCENARIO**



RISK OF USING B-BASIS ALLOWABLE



PROBABILITY OF FAILURE = $\iint_R P'_s P'_L dx dy$
 IN ONE LIFETIME FOR
 A SINGLE AIRCRAFT

R = REGION WHERE LOAD
 EXCEEDS STRENGTH

PROBABILITY OF FAILURE = 1.5×10^{-3}
 IN ONE LIFETIME FOR
 A SINGLE AIRCRAFT



TASK II ANALYSES

- STRESS ANALYSIS
- DAMAGE TOLERANCE ANALYSIS
- DURABILITY ANALYSIS
- NUCLEAR WEAPONS EFFECTS ANALYSIS
- NON-NUCLEAR WEAPONS EFFECTS ANALYSIS

TASK II TESTS

DESIGN DEVELOPMENT TESTS

BUILDING BLOCK APPROACH

- COUPONS
- ELEMENTS
- SUBCOMPONENTS
- COMPONENTS



DESIGN DEVELOPMENT TESTS

BATTLE DAMAGE TESTS

- INCLUDES ENVIRONMENTALLY CONDITIONED TEST SPECIMENS
- BUILDING BLOCK APPROACH
- DAMAGE BASED ON SPECIFIED THREAT FOR WEAPON SYSTEM
- DAMAGE STRUCTURE MUST MEET IN-FLIGHT EVIDENT RESIDUAL STRENGTH REQUIREMENT
- REPAIRABILITY REQUIREMENTS FOR EACH WEAPON SYSTEM



DESIGN DEVELOPMENT TESTS

STRENGTH TESTS

- INCLUDES ENVIRONMENTALLY
CONDITIONED TEST SPECIMENS
- BUILDING BLOCK APPROACH
- B-BASIS KNOCKDOWN FOR
SUBCOMPONENT AND
COMPONENT TESTS
- STRAIN GAGED FOR FULL
SCALE TEST CORRELATION
- TESTS TO INTERROGATE FOR
ENVIRONMENTALLY INDUCED
FAILURE MODES



DESIGN DEVELOPMENT TESTS

DAMAGE TOLERANCE TESTS

- INCLUDES ENVIRONMENTALLY CONDITIONED TEST SPECIMENS
- BUILDING BLOCK APPROACH
- DAMAGE
 - HIGH ENERGY IMPACT
 - SCRATCHES
 - DELAMINATIONS
- UPPER BOUND SPECTRUM
- MINIMUM-TWO LIFETIME TEST AND MEET RESIDUAL STRENGTH REQUIREMENTS
- SENSITIVITY TESTS



INITIAL FLAW/DAMAGE ASSUMPTIONS

FLAW/DAMAGE TYPE	FLAW/DAMAGE SIZE
SCRATCHES	SURFACE SCRATCH 4.0 INCHES IN LENGTH AND 0.02 INCH DEEP
DELAMINATION	INTERPLY DELAMINATION EQUIVALENT TO A 2.0-INCH DIAMETER CIRCLE WITH DIMENSIONS MOST CRITICAL TO ITS LOCATION
IMPACT DAMAGE	DAMAGE FROM A 1.0-INCH DIAMETER HEMISPHERICAL IMPACTOR WITH 100 FT-LB OF KINETIC ENERGY OR WITH THAT KINETIC ENERGY REQUIRED TO CAUSE A DENT 0.10 INCH DEEP WHICHEVER IS LEAST.



RESIDUAL STRENGTH REQUIREMENTS

<u>PXX*</u>	<u>DEGREE OF INSPECTABILITY</u>	<u>TYPICAL INSPECTION INTERVAL</u>	<u>MAGNIFICATION FACTOR</u>
P _F E	IN-FLIGHT EVIDENT	ONE FLIGHT**	100
P _G E	GROUND EVIDENT	ONE DAY (TWO FLIGHTS)**	100
P _W V	WALK-AROUND VISUAL	TEN FLIGHTS**	100
P _S V	SPECIAL VISUAL	ONE YEAR	50
P _D M	DEPOT OR BASE LEVEL	1/4 LIFETIME	20
P _L T	NON-INSPECTABLE	ONE LIFETIME	20

*PXX = MAXIMUM AVERAGE INTERNAL MEMBER LOAD THAT WILL OCCUR ONCE IN N TIMES THE INSPECTION INTERVAL. WHEN P_DM OR P_LT IS DETERMINED TO BE LESS THAN THE DESIGN LIMIT LOAD, THE DESIGN LIMIT LOAD SHOULD BE THE REQUIRED RESIDUAL STRENGTH LOAD LEVEL. PXX NEED NOT BE GREATER THAN 1.2 TIMES THE MAXIMUM LOAD IN ONE LIFETIME, IF PXX IS GREATER THAN DESIGN LIMIT LOAD.

**MOST DAMAGING DESIGN MISSION



DESIGN DEVELOPMENT TESTS

DURABILITY TESTS

- INCLUDES ENVIRONMENTALLY
CONDITIONED TEST SPECIMENS
- BUILDING BLOCK APPROACH
- DAMAGE
 - LOW ENERGY IMPACT
(TOOL DROP, HAIL,
RUNWAY DEBRIS)
- UPPER BOUND SPECTRUM
- MINIMUM-TWO LIFETIME TEST
AND MEET RESIDUAL IMPAIRMENT
REQUIREMENTS
- SENSITIVITY TESTS



LOW ENERGY IMPACT (TOOL DROP)

ZONE	DAMAGE SOURCE	DAMAGE LEVEL	REQUIREMENTS
① HIGH PROBABILITY OF IMPACT	0.5" DIAMETER SOLID IMPACTOR - LOW VELOCITY - NORMAL TO SURFACE	VISIBLE (0.1" DEEP DENT) 6 FT-LB MAX	- NO FUNCTIONAL IMPAIRMENT OR OR STRUCTURAL REPAIR REQUIRED FOR TWO DESIGN LIFETIMES AND AND NO WATER INTRUSION - NO VISIBLE DAMAGE FROM A SINGLE 4 FT-LB IMPACT
② LOW PROBABILITY OF IMPACT	SAME AS ZONE ①	SAME AS ZONE ①	NO FUNCTIONAL IMPAIRMENT AFTER TWO DESIGN LIFETIMES AND NO WATER INTRUSION - AFTER FIELD REPAIR IF DAMAGE IS VISIBLE



LOW ENERGY IMPACT (HAIL AND RUNWAY DEBRIS)

ZONE	DAMAGE SOURCE	DENSITY	REQUIREMENTS
ALL VERTICAL AND UPWARD FACING HORIZONTAL SURFACES	HAIL • 0.8" DIAMETER • SP. GR = 0.9 • 90 FT/SEC • NORMAL TO HORIZONTAL SURFACES • 45° ANGLE TO VERTICAL SURFACES	UNIFORM DENSITY 0.8" ON CENTER	• NO FUNCTIONAL IMPAIRMENT OR STRUCTURAL REPAIR REQUIRED FOR TWO DESIGN LIFETIMES AND NO WATER INTRUSION • NO VISIBLE DAMAGE
STRUCTURE IN PATH OF DEBRIS	RUNWAY DEBRIS • 0.5" DIAMETER OBJECT • SP. GR = 3.0 • VELOCITY APPROPRIATE TO WEAPON SYSTEM	—	• NO FUNCTIONAL IMPAIRMENT FOR TWO DESIGN LIFETIMES AND NO WATER INTRUSION - AFTER FIELD REPAIR IF DAMAGE IS VISIBLE



TASK III

FULL SCALE TESTING

- **STATIC TESTS**
 - REQUIRED FOR COMPOSITE STRUCTURE
- **DURABILITY TESTS**
 - NOT REQUIRED FOR COMPOSITE STRUCTURE IF DESIGN DEVELOPMENT TESTS MEET OBJECTIVES
- **DAMAGE TOLERANCE TESTS**
 - NOT REQUIRED FOR COMPOSITE STRUCTURE IF DESIGN DEVELOPMENT TESTS MEET OBJECTIVES



FULL SCALE TESTING

416

- **CRITICAL ENVIRONMENTALLY INDUCED FAILURE MODE**

STATIC TESTS

YES

NO

- **TEST AT ROOM TEMPERATURE WITHOUT SPECIAL MOISTURE CONDITIONING**
- **TEST TO 150% DESIGN LIMIT LOAD CONDITION**
- **STRAIN GAGING TO CORRELATE WITH DESIGN DEVELOPMENT TESTS**
- **TEST WITH ENVIRONMENTALLY CONDITIONED ARTICLE**
- **TEST TO 150% DESIGN LIMIT LOAD CONDITION**
- **STRAIN GAGING TO CORRELATE WITH DESIGN DEVELOPMENT TESTS**



TASK IV

FORCE MANAGEMENT DATA PACKAGE

- LOADS/ENVIRONMENTAL SPECTRUM SURVEY
- AND
- INDIVIDUAL AIRCRAFT TRACKING PROGRAM
- MUST BE CAPABLE OF RECORDING HIGH LOAD EVENTS THAT ARE POTENTIALLY DAMAGING TO COMPOSITE STRUCTURES



RISK OF USING B-BASIS ALLOWABLE

STRENGTH

$$P_S(x) = 1 - \exp \left[-\left(\frac{x}{\beta_S} \right)^{\alpha_S} \right]$$

$$\alpha_S = 20$$



LOAD

$$P_L(y) = \exp \left[-\left(\frac{y}{\beta_L} \right)^{\alpha_L} \right]$$

$$\alpha_L = 6$$



PROBABILITY OF FAILURE = $\iint_R P'_S P'_L \, dx \, dy$
IN ONE LIFETIME FOR
A SINGLE AIRCRAFT

R = REGION WHERE LOAD
EXCEEDS STRENGTH

PROBABILITY OF FAILURE = 1.5×10^{-3}
IN ONE LIFETIME FOR
A SINGLE AIRCRAFT



CONCLUSIONS

- LABORATORY PROGRAMS HAVE PROVIDED THE CONFIDENCE TO USE COMPOSITES IN FLIGHT CRITICAL STRUCTURE OF NEW WEAPON SYSTEMS
- THE AIRCRAFT STRUCTURAL INTEGRITY PROGRAM CURRENTLY CONTAINS THE NECESSARY ELEMENTS FOR FULL SCALE DEVELOPMENT OF COMPOSITE STRUCTURES

Damage Tolerance of Composites Criteria and Evaluation

**NASA Workshop on Impact Damage to Composites
NASA Langley Research Center
Hampton, Virginia**

March 19-20, 1991

**Ray Horton
Boeing Commercial Airplane Group
Seattle, Washington**

A1891.01 8

Presentation Areas

- Air Force criteria development
- Boeing Commercial Airplane criteria
- Air Force contract test approach

Air Force Damage Tolerance Criteria Development

Approach

- Basic objectives
- Flaw selection
- Loading requirement
- Industry and Air Force
 - Participation
 - Concurrence

Basic Objectives

- **Safety enhancement**
- **Maximum retention of elements of metals requirements**
- **Realistic compliance requirements**
- **Minimum impact on design / weight / cost**

Composite Versus Metals Properties

Condition		Composite behavior relative to metals
Load-strain relationship		More linear strain to failure
Notch sensitivity	Static	Greater sensitivity
	Fatigue	Less sensitivity
Transverse properties		Weaker
Mechanical properties variability		Slightly higher
Sensitivity to aircraft hydrothermal environment		Greater
Damage growth mechanism		Crack propagation, delamination, instead of fatigue crack growth as cracks

Manufacturing Flaw / Damage Sources

- **Materials**
 - Material specification controlled – all
- **Layup / processing**
 - Process specification controlled – most
- **Assembly**
 - Assembly specification controlled – some

In-Service Flaw / Damage Sources

- Servicing — fueling, inspection and maintenance access, handling / moving
 - Access damage — access attachment — fastener holes — exposed edges gouges, scratches
 - Impact damage — service carts, work stands, toolbox, tools
- Flight / taxi
 - Flight: hail, bird and detached fairing— impact / penetration damage
 - Taxi: runway debris, blown tires— impact / penetration damage
- Repair — processing and assembly
 - Similar to manufacturing consideration

Concerns and Considerations

- **Damage not included**
- **Battle damage**
- **Engine disintegration damage**
- **Lightning damage**
- **Bird impact damage**
- **Hall damage**
- **Flaws not included**
- **Porosity**
- **Fastener hole cracks**

Lightning Damage Should Not Be Considered for Damage Tolerance Requirements


- **Rationale**
 - Lightning protection needed for other reasons (i.e., fuel ignition etc.)
 - Lightning strike damage will be evaluated in protection system development; protection system should preclude damage that is not visual or significant when not a known event
 - Strike assumptions are conservative, as well as testing techniques
 - Inspection of damage will require assessment for both protection and structural. Significant damage visually detectable
 - Strike usually a known event
 - Damage definition difficult
 - Impact and penetration should blanket this case

§ Initial Flaw / Damage Assumptions

Flaw / Damage Type	Flaw / Damage Size (1)
Scratches	Assume the presence of a surface scratch that is 4.0 in long and 0.02 in deep
Delamination	Assume the presence of an Interply delamination that has an area equivalent to a 2.0-in diameter circle with dimensions most critical to its location (2)
Impact Damage	Assume the presence of damage caused by the impact of a 1.0-in diameter hemispherical impactor with 100 ft-lb of kinetic energy or with that kinetic energy required to cause a dent 0.10 in deep, whichever is least

- (1) For limited access areas such as the interior of the wing, the contractor shall have the option of proposing an inspection procedure before closeout which will allow the assumed damage area size to be reduced
- (2) This requirement also accounts for delamination that might occur and be nondetected as a result of in-service repair

Impact Damage Assumptions




Residual Strength Load Requirements

P_{XX}^*	Degree of Inspectability	Typical Inspection Interval	Period of Unrepaired Service Usage	Magnification Factor, M
P_{FE}	In-flight evident	One flight	Return to base	100
P_{GE}	Ground evident	One flight	Two flights of most damaging design mission	100
P_{WV}	Walk-around visual	Ten flights	Five inspection intervals	100
P_{SV}	Special visual	One year	Two inspection intervals	50
P_{DM}	Depot or base level	1 / 4 lifetime	Two inspection intervals	20
P_{LT}	Noninspectable	One lifetime	Two lifetimes	20

* P_{XX} = Maximum internal member load that will occur once in M times the appropriate inspection interval


Where P_{DM} or P_{LT} is determined to be less than design limit load, the design limit load shall be the required residual strength load level. P_{XX} need not be greater than 1.2 times the maximum load in one lifetime, if greater than design limit load

Impact Damage and Requirement Metal Structure




ORIGINAL PAGE IS
OF POOR QUALITY

Damage Growth Detection and Restoration Cycle for Metal Structure



ORIGINAL PAGE IS
OF POOR QUALITY

Impact Damage and Requirement Composite Structure



Conservative Assumptions

- That an undetected 100 ft lb impact is a rogue event
- That the occurrence is at a most critical location
- That the occurrence will account for worst case environmental conditions
- That with the above combined conditions, the airplane will experience an exceptionally high load

Industry and Air Force Participation and Concurrence

- **Air Force**
 - **Reviewed approach**
 - **Concurrence**
 - **Flaw selection**
 - **Compliance requirements**
- **AIA**
 - **Two reviews**
 - **General acceptance**
 - **Compliance requirement realistic**

FAA Advisory Circular AC-107A

"It should be shown that impact damage that can be realistically expected from manufacturing and service, but not more than the established threshold of detectability for the selected inspection procedure, will not reduce the structural strength below ultimate load capability. This can be shown by analysis supported by test evidence, or by tests at the coupon, element or subcomponent level"

Boeing Commercial Airplane Design Criteria

Damage Tolerance Design Philosophy

Composite primary structure shall meet the safety standards and the economic maintenance standards of current transport airplanes.

Strength, durability, and damage tolerance allowables and stiffness properties shall include the effects of adverse environments such as moisture, fuel, hydraulic fluid, and temperature.

Internal loads caused by environmentally induced strains shall be combined with ultimate, residual strength, and operating loads.

Structure shall be designed to be resistant to damage from normal handling in manufacturing or airline environments. Equivalence to service-demonstrated successful applications shall be obtained.

Repaired structure shall meet the requirements for static strength, durability, damage tolerance, and stiffness. Fixed structure shall be designed for on-airplane repair.

Boeing Commercial Airplane Design Criteria

Ultimate Strength

Accidental Impact Damage

It shall be shown that impact damage that can be realistically expected from manufacturing and service, but not more than the established threshold of detectability for the selected inspection procedure, will not reduce the structural strength below ultimate load capability. (FAA AC 20-107A, 6.g.)

Composite primary structure shall be capable of sustaining ultimate load with isolated impact damage, inflicted by any likely energy source that cannot be seen visually. To assure that this criteria is met, the structure shall be designed to sustain ultimate load after being impacted with the minimum energy source (up to 1,200 in-lb) that is required to produce impact damage that is visible from a distance of 5 feet with the unaided eye under normal structural inspection conditions.

Boeing Commercial Airplane Design Criteria

Ultimate Strength

Ground hail

Structure exposed to ground hail shall sustain ultimate load and not require immediate structural repair following impacts as specified below, spaced 12-in apart at critical locations.

Structure type	Surface position	Hail diameter, in	Impact energy, in-lb
Fixed primary	Horizontal	2.5	500
	Vertical	2.5	300
Removeable primary	Horizontal	1.5	70
	Vertical	1.5	40

Lightning strike

Primary structure exposed to lightning strike shall sustain ultimate load and not require immediate structural repair following the maximum energy strike occurring at the considered location once in the life of the airframe.

Boeing Commercial Airplane Design Criteria

Damage Growth and Residual Strength

Composite primary structure shall be designed to preclude detrimental damage growth under operating loads following isolated impact damage at the energy levels defined for ultimate strength requirements with accidental impact damage.

Composite primary structure shall be designed damage tolerant, i.e., it shall be shown by analysis or test that fatigue, corrosion, or accidental damage will be detected by the structural inspection plan and prevent catastrophic failure during the operational life of the airframe.

Primary composite structure shall satisfy regulatory residual strength requirements (FAR 25.571(b)) following failure or obvious partial failure of a single structural unit (e.g., a stiffener with two skin bays, a chord with one skin bay, or similar combinations).


**AIR FORCE DAMAGE TOLERANCE REQUIREMENTS
VALIDATION PROGRAM**

Typical Large Aircraft Multirib Wing Design

Technical
Illustration
of a Typical Large Aircraft Multirib Wing Construction

Typical Large Aircraft Multirib Wing Construction

Building-Block Test Approach



Coupon Basic Property Test Matrix

Specimen description	Static			Fatigue			
	1			Const amplitude			
	RT dry	RT wet	-75°F dry	RT dry	RT wet	-75°F dry	Spectrum
Delamination	•	•	•	•	•	•	•
200-in-lb Impact damage	•			•			
350-in-lb Impact damage	•			•			•

Material: AS6/2220-3

Specimen: 0.25 x 5.0 x 10.0



1 R = 10




Test Setup

G326688 060

Location of Delaminations in 3-Stringer Panels





447



Panel After Failure

Impact Damage on 3-Stringer Panels Ultrasonic Pulse Echo Readings



1200-lb impacts
1-in-dia tip

Impact Damage on 3-Stringer Panel Ultrasonic Pulse Echo Readings



**Multiple Impact
Damage**




**Internal Stringer Flange
Impact Damage**

ORIGINAL PAGE IS
OF POOR QUALITY

Multiple Impact Static Test Results



Failed Panel



- Single Impact 1200 in-lb
- Multiple Impact 1200 in-lb + 240 in-lb
- Adjusted value

• AS4/3501-6

ORIGINAL PAGE IS
OF POOR QUALITY

TG1074B 003

Damage Growth Pattern



DSN 17

INSPECTION LEVEL

0.0-0.25t

0.25-0.75t

0.75-1.00t



Loading Lifetimes

Initial

0.25

0.5

0.5+

1.5-2.0

• 10/80/10 Skin layout

• AS4/3501-6

Effect of Stitching



Stitched Panel

Stitching

- 0.25 inch pitch and row spacing
- Thru skin, planking, and stringer flange edge
- Kevlar thread

Other

- 10/80/10 Skin layup
- 1200 in-lb impact
- Tested wet at 180 F°

Results

- Failed at 114% of control

TG1072B 004

THERMOPLASTIC - PEEK APC - 2
First Panel After Initial Consolidation
Showing Void Areas



ORIGINAL PAGE IS
OF POOR QUALITY

453

TG1099B 004



THERMOPLASTIC - PEEK APC - 2
Panel After Tool
Rework and Reconsolidation



ORIGINAL PAGE IS
OF POOR QUALITY

TG1100B 004

Comparison of Post-Impact Failure Strain — AS4 / APC-2 (PEEK) Versus AS4 / 3501-6



Failed Panel


100 ft-lb impact

455

ORIGINAL PAGE IS
OF POOR QUALITY

G32080B 056

Fatigue Test Results of Impacted Laminates



Material	Layout	Impact In-lb
○ ASA/PEEK	10/50/10	250
⊙ ASA/PEEK	10/50/10	500
◇ ASA/PEEK	40/50/10	250
▽ ASA/PEEK	40/50/10	500
△ AS67220-3	40/50/10	200
▽ AS67220-3	40/50/10	350

Notes:

R = 10


70°F, dry

0.25 X 5.0 X 10.0


*Residual static strength

Task II 5-Stringer Test Panels

Prior to Test




BLADE-STIFFENED PANEL




I-STIFFENED PANEL

Typical Blade-Stiffened Panel Failure

5-Stringer Panel



SKIN SIDE




STRINGER SIDE


00000000 000

Typical I-Stiffened Panel Failure

5-Stringer Panel



SKIN SIDE



STIFFENER SIDE

ORIGINAL PAGE IS
OF POOR QUALITY

Northrop Wing Box Test

- Conventional composite fighter wing design
- Multispar, hard skin
- Mechanically fastened upper skin to spar
- Harsh load cycling requirement



Northrop Fighter Wing Test Box

ORIGINAL PAGE IS
OF POOR QUALITY


THE NEW YORK PUBLIC LIBRARY

ASTOR LENOX TILDEN FOUNDATION
455 FIFTH AVENUE
NEW YORK 17, N. Y.

461

ORIGINAL PAGE IS
OF POOR QUALITY


3-Stringer Panel Design



- Panel size: 22.4 in x 19.5 in
- Stringer spacing: 8 in
- Design load: 25k/in
- Ultimate design strain: 0.005
- Material: AS4/3501-6
- Nominal ply thickness: 0.0073

TO16628 003

Multispair Wing Box Test



463

ORIGINAL PAGE IS
OF POOR QUALITY

Multispar Wing Box Failure Summary

Failure occurred after 355 flight cycles (0.07 lifetimes) at a maximum spectrum load.

The box had been designed to the following upper skin strain levels without consideration for damage tolerance -

- Design ultimate strain - 0.004**
- Design limit strain - 0.00267**
- Maximum spectrum strain - 0.00325**

The box would require redesign to meet damage tolerance requirements.


Boeing Wing Box Test

- Advanced design composite transport wing
- Multirib, soft skin
- Co-cured stiffeners with integral reinforcing planks
- Moderate load cycling requirement



Boeing Transport Wing Test Box

Side Elevation View of Test Setup




Q31690 054

ORIGINAL PAGE IS
OF POOR QUALITY

Multirib Wing Box In Loading Fixture

Installation of Strain Gages



TG1145B 005

467

ORIGINAL PAGE IS
OF POOR QUALITY

Upper Surface Panel Compression Failure



469

ORIGINAL PAGE IS
OF POOR QUALITY

TG1260B 007

Upper Surface Panel Compression Failure Close-up



TG1261B 007

Conclusions

- **Failure was in the test box upper surface panel and initiated at an induced impact damage location**
- **The strain at failure was 4200 μ in/in, at 105% of the design goal**
- **The test met all qualification requirements**

Air Force Damage Tolerance Program Results

- Establishment of damage tolerance specification requirements.
- Development and use of a building-block test approach to demonstrate specification compliance.
- Evaluation of a tough thermoplastic material to demonstrate superior damage tolerance properties.
- Development of analysis methods to predict damage characteristics.
- Testing to investigate methods and materials to improve damage tolerance.
- Assessment of the characteristic ability of the representative composite fighter and transport structure to resist battle damage.



Report Documentation Page

1. Report No. NASA CP-10075	2. Government Accession No.	3. Recipient's Catalog No.	
4. Title and Subtitle NASA Workshop on Impact Damage to Composites		5. Report Date July 1991	
		6. Performing Organization Code	
7. Author(s) C. C. Poe, Jr., Compiler		8. Performing Organization Report No.	
		10. Work Unit No. 505-63-50-04	
9. Performing Organization Name and Address NASA Langley Research Center Hampton, VA 23665-5225		11. Contract or Grant No.	
		13. Type of Report and Period Covered Conference Publication	
12. Sponsoring Agency Name and Address National Aeronautics and Space Administration Washington, DC 20546-0001		14. Sponsoring Agency Code	
15. Supplementary Notes Primarily viewgraphs.			
16. Abstract This document is a compilation of the slides presented at the NASA Workshop on Impact Damage to Composites held on March 19 and 20, 1991, at Langley Research Center, Hampton, Virginia. The Mechanics of Materials Branch of NASA Langley Research Center sponsored the workshop. The objective of the workshop was to review technology for evaluating impact-damage tolerance of composite structures and identify deficiencies. Research, development, design methods, and design criteria were addressed. Actions to eliminate technology deficiencies were developed. A list of those actions and a list of attendees is also included.			
17. Key Words (Suggested by Author(s)) polymer-matrix composites aerospace structures impact damage residual strength impact mechanics		18. Distribution Statement Unclassified - Unlimited Subject Category - 24	
19. Security Class. (of this report) Unclassified	20. Security Class. (of this page) Unclassified	21. No. of pages 483	22. Price A21

END

DATE

FILMED

OCT 4 1991